


Miller Haul Route

Guernsey County



Driving Directions

From the west:

From the intersection of US 22 and OH 513 west of Londonberry, drive east on US 22 for 2.8 miles.

Turn right onto TR 93, Jasper Road.

Drive 1.3 miles to lease road on the right.

From the east:

From the intersection of US 22 and CR 95 in Londonberry, drive west on US 22 for 1.4 miles.

Turn left onto TR 93, Jasper Road.

Drive 1.3 miles to lease road on the right.