


Ridgetop Haul Route

Belmont County

For all vehicles including Semis under 100,000#



Directions:

From the intersection of OH 647 and CR 2, Deep Run Road south of Mt. Pleasant, drive southeast on CR 2 for 1.8 miles.

Bear left onto CR 16, Dixon Run.

Drive 0.5 miles. Access will be on the left.

For vehicles over 100,000 pounds, contact a Gulfport representative.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>