


Robert Haul Route

Monroe County



Driving Directions:

From the intersection of OH 800 and OH 78 at the traffic signal in the middle of Woodsfield, go east on OH 78 for 4.3 miles.

Turn left on CR 30, Mt. Carrick Road.

Drive 0.3 mile and turn left onto TR 2308.

Drive 0.4 mile. Access will be on the left.

Note: CR 30 is also 11.5 miles west of OH 7 in Clarington. This route is not shown.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Amy Zwick at 740-472-2537, email azwick@monroecountyengineer.com

More information can be found at <http://monroecountyohio.com/government/engineer/index.php>