


Roger (Brown W) Haul Route
Monroe County



Driving Directions

From the intersection of OH 800 and OH 26 south of Woodsfield, Go west on OH 26 for 5.8 miles.

Turn right onto CR 12, Hartshorn Ridge Road for 2.2 miles.

Turn right onto CR 48, Conner Ridge Road.

Drive 1 mile. Entrance will be on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Amy Zwick at 740-472-2537, email azwick@monroecountyengineer.com

More information can be found at <http://monroecountyohio.com/government/engineer/index.php>