


Ryser Haul Route

Harrison County



Driving Directions

All traffic must use the same route regardless of their direction of approach.

From the intersection of US 22 and OH 331 in Piedmont, go north on CR 16, Old Piedmont Road for 1 mile.

Turn left onto CR 62, Scott Hill Road. Drive for 1.2 miles to the entrance on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit.

Contact Kris Miller at 740-942-8867. More information can be found at

<http://www.harrisoncountyohio.org/county-engineer-permits>