


Shimble Haul Route

Belmont County



From the west:

From I-70

Going eastbound on 70, take Exit 220 and turn right onto CR 214, Bellaire High Ridge Road.

Drive 1.9 miles and turn right onto CR 30, Dixon Run Road.

Drive 0.1 mile across the bridge and turn right onto TR 317, McGregor Hill Road.

Drive 0.5 mile. Access will be on the right.

From I-470

Going eastbound on I-470, take exit 3 and turn left onto CR 214, Bellaire High Ridge Road.

Drive 1.1 miles and turn left onto CR 30, Dixon Run Road.

Drive 0.1 mile across the bridge and turn right onto TR 317, McGregor Hill Road.

Drive 0.5 mile. Access will be on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>

From the East:

From I-70

Going westbound on I-70, take Exit 220 and turn left onto US 40.

Drive 0.1 mile and turn left onto CR 214, Bellaire High Ridge Road.

Drive 2.0 miles and turn right onto CR 30, Dixon Run Road.

Drive 0.1 mile across the bridge and turn right onto TR 317, McGregor Hill Road.

Drive 0.5 mile. Access will be on the right.

From I-470

Going westbound on I-470, take exit 3 and turn right onto CR 214, Bellaire High Ridge Road.

Drive 1 mile and turn left onto CR 30, Dixon Run Road.

Drive 0.1 mile across the bridge and turn right onto TR 317, McGregor Hill Road.

Drive 0.5 mile. Access will be on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>