



Smith Haul Route

Belmont County



Smith Haul Route

Driving Directions

From the east and north and all I-70/I-470 traffic:

From the I-470 and OH 7 intersection west of Wheeling, drive 8.8 miles south on OH 7.

Turn right onto TR 534, Broadview Road.

Drive 1.8 miles and turn left onto TR 296, Cash Ridge Road.

Drive 0.9 mile and turn left onto TR 614, Old Workman Road.

Drive 0.25 mile. Access will be on the left.

From the south:

From the intersection with the Moundsville Bridge in Dilles Bottom, drive north on OH 7 for 1.2 miles.

Turn left onto TR 534, Broadview Road.

Drive 1.8 miles and turn left onto TR 296, Cash Ridge Road.

Drive 0.9 mile and turn left onto TR 614, Old Workman Road.

Drive 0.25 mile. Access will be on the left.

From the west below I-70:

From the OH 9 and OH 147 intersection in Centerville, OH (OH 9 south of St. Clairsville), drive east on OH 147 for 6.2 miles.

Turn right onto CR 48, Wegee Road just past the gasoline station/corner store.

Drive for 0.9 mile and turn right onto TR 296, Cash Ridge Road.

Drive 1.4 mile and keep left on Cash Ridge Road at the intersection.

Drive 3 miles. And turn right onto TR 614, Old Workman Road.

Drive 0.25 mile. Access will be on the left.