


Starvaggi Haul Route

Belmont County



Driving Directions from the north:

From the intersection of OH 647 and CR 2, Deep Run Road, south of Mt. Pleasant, drive east on CR 2 for 1.8 miles to the intersection with CR 16, Nixon Run Road.

Bear left to continue on CR 2.

Drive another 1.8 miles and turn left onto TR 469, Beech Spring Road. (May be listed as Pattons Run or Nixon Run).

Drive 0.7 mile. Access will be on the left.

From the east, west and south:

From the intersection of I-470 and OH 7, drive north for 5.5 miles and turn left on CR 4, Glenns Run Road.

Drive 0.5 mile and turn right on CR 16, Nixon Run Road.

Drive 2.8 miles and turn right onto CR 2, Deep Run Road. Trucks must continue straight on use the turn around on the left 0.7 miles ahead.

Drive 1.8 miles and turn left onto TR 469, Beech Spring Road. (May be listed as Pattons Run or Nixon Run).

Drive 0.7 mile. Access will be on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>

NOTE: All trucks over 100,000 must use alternate route on Barnes Road. Contact Gulfport for more information.