



## Sunset to Ware Rig Move






### Driving Directions


**At the bottom of the lease road, turn right on TR 458, Buckeye Run.**

**Drive 0.4 mile and turn left onto US 250.**

**Drive 2.8 miles to a stop sign.**




**Cross the intersection and turn left onto RT 7 north.**



**Drive 4.6 miles on RT 7 north and turn left onto CR 4, Glens Run Road.**

**Drive 0.6 mile and turn right onto CR 16, Nixon Run Road.**



**Drive 2.4 miles on CR 16 and Turn left onto TR 464, Treadway Road.**

**Drive 0.1 mile and turn right onto TR 466, Barnes Road.**

**Drive 0.3 mile and turn left into lease road.**

**Total distance is 10 miles, excluding lease roads.**