


Thornberry Haul Route

Belmont County

From the north:



Driving Directions

From the intersection of OH 148 and OH 800 south of Barnesville, drive 5.1 miles south on OH 800 through Somerton.


At the bottom of the hill, turn left onto TR 35, Grimes-Skinner Road.

Drive 0.15 mile. Access will be on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160.

Permit information can be found at <http://belmontcountyengineer.com/data/forms/>

From the south:



Driving Directions

From the intersection of OH 145 and OH 800 in Malaga, drive 3.1 miles north on OH 800.

Turn right onto TR 35, Grimes-Skinner Road.

Drive 0.15 mile. Access will be on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160.

Permit information can be found at <http://belmontcountyengineer.com/data/forms/>