


Tiger Haul Route

Belmont County



Driving Directions

From the north and west:

- 1. From the intersection of OH 9 and OH 147 in Centerville, South of St. Clairsville, drive 6 miles east on OH 147.**
- 2. Turn right onto CR 48, Wegee Road for 0.9 mile.**
- 3. Turn right onto TR 296, Cash Ridge for 1.4 miles.**
- 4. Turn right onto TR 298, Lockwood Run Road for 0.5 mile.**
- 5. Turn right onto TR 293, Kirkland Hill Road for 1.4 miles.**
- 6. Access will be on the right.**

From the south and east:

- 1. From the overpass for the Moundsville Bridge on OH 7, drive north on OH 7 for 2.4 miles.**
- 2. Turn left onto TR 534, Broadview Road.**
- 3. Drive 2.2 miles and turn left onto TR 296, Cash Ridge Road.**
- 4. Drive 3 miles and turn left onto TR 298, Lockwood Run Road.**
- 5. Drive 0.5 miles and turn right onto TR 293, Kirkland Hill Road.**

Drive 1.4 miles. Access will be on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Belmont County Engineers office at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>