


Triple B Haul Route

Belmont County



Driving Directions

From the East:

Take Exit 208 on I-70. Turn right for .5 mile.

Turn left at the stop sign onto US 40 for 3.5 miles.

Turn right at the stop sign onto CR 100, Egypt North Road for 1.7 miles.

Turn right onto TR 397 Shepherd Road/Coal Run for .5 miles.

Turn right onto TR 397 Coal Run for 3.3 miles.

Access is on the left.

From the West:

Take Exit 204 on I-70.

Turn right at the stop sign.

Go .2 miles to stop sign and go straight across the intersection onto Egypt North Road for 1.7 miles.

Turn right onto TR 397 Shepherd Road/Coal Run for .5 miles.

Turn right onto TR 397 Coal Run for 3.3 miles. Access is on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>