


Vozar Haul Route

Harrison County



Driving Directions

From the west:

At the intersection of US 22 and OH 800 South east of Londonderry, Go east on US 22 for 2.8 miles.

Turn left onto TR 308, McElhaney Road.

Go 0.3 mile. Entrance will be on the right.

From the east:

At the intersection of US 22 and OH 331 in Piedmont, go west on US 22 for 0.7 miles.

Turn right onto TR 308, McElhaney Road.

Go 0.3 mile. Entrance will be on the right.