


Wesley Haul Route

Belmont County



Driving Directions

1. From OH 800 in Barnesville, turn west onto 147 for 3.4 miles.
2. Turn left onto OH 147 for 1.1 miles.
3. Turn left onto OH 379 for 1.4 miles.
4. Turn left onto CR 128, Boston Road/Main Street for 3.2 miles.
5. Turn left onto TR 21, Mason Road for 2.5 miles.
6. Access is on left going up the hill.