

Cold Work Permit

Permit Number: PTW/CP/011

A - General Information

Permit Issuer Dept: Safety	Name: Permit Issuer
Permit Acceptor Dept: Operations	Name: Permit Acceptor
Contractor: ABC Engineering Services	Supervisor: manoj dhande
Proposed Work: cleaning	

B - Work Description

Equipment Number: DC1234	Location: plant
Proposed Work in Detail: Cleaning in drainage, cleanng	
Any Hazard Activity: ✓ Lift & shift by equipment ✓ Exposure to hazardous chemical ✓ Any other: tereere	
Valid on Date: 2026-09-17 Time From: 19:53 Time To: 22:56	

C - Hazard Identification

Hazards from equipment/installations:	
✓ Moving parts	✓ Hot surfaces
Hazards from work type/location:	
✓ Underground pipe/cable	
Other Hazards: Na	Other Hazards in accordance with Permit No: nothng

D - Protective Measures - Hazard Assessment Checklist

Hazard assessment & compliance checklist	Yes	No	Measure Implemented Sign.	Measure Lifted Sign.
D-3.9 Are mandatory Personal protective equipment provided and used by employees on the job PPE_2: Mask PPE_1: Gloves	✓		Permit Issuer	
D-3.10 Additional PPEs recommended for job are provided			Permit Issuer	
D-5.9 Is adequate illumination provided	✓		Permit Issuer	
D-5.9.1 Other			Permit Issuer	
D-8 Other units affected		✓	Permit Issuer	
D-9 Safety briefing/instruction provided to persons authorised for acceptance	✓		Permit Issuer	
D-3.1 Deactivate power supply and testing		✓	Permit Issuer	
D-3.2 Is the work area barricaded for unauthorised entry		✓	Permit Issuer	
D-3.3 Is work on elevated platform if any	✓		Permit Issuer	
D-3.4 Is work platform ladder inspected and is free of defect	✓		Permit Issuer	
D-3.5 Is any portable electrical equipment required for the job if yes has it been inspected by competent person and is safe to work	✓		Permit Issuer	
D-3.6 Are workmen involved in the job informed about the risk associated with area and job			Permit Issuer	
D-3.7 Is the job requiring constant supervision	✓		Permit Issuer	
D-3.8 Is there any moving machine or movement of material handling equipment near-by	✓		Permit Issuer	

Hazard assessment & compliance checklist	Yes	No	Measure Implemented Sign.	Measure Lifted Sign.

E - Post-work Measures required

Item	Yes	No	Answered By
E-1. All tools and garbage removed from work place and area is clean and safe for working	✓		Permit Issuer
E-2. Other Other: done	✓		Permit Issuer

F - Approval of work permit after verification of measures

Date: _____ **Signature:** _____

(Permit Issuer) **Permit Issuer**

G - Acceptance of Permit for work to be conducted

It is confirmed that we have reviewed the measures taken and work can be undertaken safely.

Date: _____ **Name & Signature:** _____

Date: _____ **Contractor Supervisor Signature:** _____

H - Completion Report by the Person Completing the Work to the issuer dept.

The proposed work as given in the description has been completed: ☐ Yes ☐ No

Date: _____	Sign.: _____	Date: _____	Sign.: _____
(Permit Acceptor / executor)		Supervisor of the contractor	

I - Acceptance Check and withdrawal of pre-check conditions (lifting safety measures)

Date and signature of issuer _____	Remarks if any : _____	
---------------------------------------	---------------------------	--