

Cold Work Permit

Permit Number: PTW/CP/021

A - General Information

Permit Issuer Dept: Safety	Name: Permit Issuer
Permit Acceptor Dept: Operations	Name: Permit Acceptor
Contractor: ABC Engineering Services	Supervisor: manoj dhande
Proposed Work: rtshs	

B - Work Description

Equipment Number: DC1234	Location: dsds
Proposed Work in Detail: dwwe	
Any Hazard Activity: ✓ Lift & shift by equipment ✓ Exposure to hazardous chemical ✓ Any other: dsds	
Valid on Date: 2026-10-01 Time From: 15:22 Time To: 17:22	

C - Hazard Identification

Hazards from equipment/installations:	
✓ Moving parts	✓ Charged surface / voltage
Hazards from work type/location:	
✓ Cold stress	✓ Underground pipe/cable
Other Hazards: we	Other Hazards in accordance with Permit No: ewe

D - Protective Measures - Hazard Assessment Checklist

Hazard assessment & compliance checklist	Yes	No	Measure Implemented Sign.	Measure Lifted Sign.
3.1 Deactivate power supply and testing		✓	Permit Issuer	
3.2 Is the work area barricaded for unauthorised entry				
3.3 Is work involves on elevated platform if yes, Is work platform ladder inspected and is free from defect	✓		Permit Issuer	
3.4 Is any portable electrical equipment required for the job if yes Has it been inspected by competent person and is safe to work		✓	Permit Issuer	
3.5 Are workmen involved in the job informed about the risk associated with area and job				
3.6 Is the job requiring constant supervision	✓		Permit Issuer	
3.7 Is there any moving machine or movement of material handling equipment near-by				
3.8 Are mandatory Personal protective equipment (safety helmet, safety shoes, safety glasses provided and used by employees on the job	✓		Permit Issuer	
3.9 Additional PPEs recommended for job PPE_2: Mask PPE_1: Gloves	✓		Permit Issuer	
3.10 Is adequate illumination provided				
3.11 Other				
4 Other units affected				
4.1 Safety measure				

Hazard assessment & compliance checklist	Yes	No	Measure Implemented Sign.	Measure Lifted Sign.
5 Safety briefing/instruction provided to persons authorised for acceptance		✓	Permit Issuer	

E - Post-work Measures required

Item	Yes	No	Answered By
E-1. All tools and garbage removed from work place and area is clean and safe for working	✓		Permit Issuer
E-2. Other	✓		Permit Issuer

F - Approval of work permit after verification of measures

Date: _____ Signature: _____

(Permit Issuer) **Permit Issuer**

G - Acceptance of Permit for work to be conducted

It is confirmed that we have reviewed the measures taken and work can be undertaken safely.

Date: _____ Name & Signature: _____

Date: _____ Contractor Supervisor Signature: _____

H - Completion Report by the Person Completing the Work to the issuer dept.

The proposed work as given in the description has been completed: ☐ Yes ☐ No

Date: _____	Sign.: _____	Date: _____	Sign.: _____
(Permit Acceptor / executor)		Supervisor of the contractor	

I - Acceptance Check and withdrawal of pre-check conditions (lifting safety measures)

Date and signature of issuer _____	Remarks if any : _____	
---------------------------------------	---------------------------	--

Attachment: Safety Briefing Record for Workers put on the job				
Following workmen put on the job are explained about hazards involved with work place & precautions to be taken while performing the job.				
Name	Date	Time	Authorized workers (Signature)	Safety briefing provided by (Signature) supervisor of the contractor if any
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		
	/ /	:		