

COLD WORK PERMIT

Permit Number: PTW/CP/006

A - General Information

Permit Issuer Dept: Safety

Permit Acceptor Dept: Operations

Name: Permit Issuer

Name: Permit Acceptor

B - Work Description

Equipment Number: EQ123

Location: plant3

Proposed Work:

tesutbg5

Valid on Date: 2026-09-08

Time From: 21:20

Time To: 17:22

C - Hazard Identification

Hazards from equipment/installations:

✓ Moving parts

✓ Hot surfaces

✓ Cold surfaces

Hazards from work type/location:

✓ Electrical shock

✓ Dust

✓ Cold stress

Other Hazards: NA

Other Hazards in accordance with Permit No: Gloves

D - Protective Measures - Hazard Assessment Checklist

Hazard assessment & compliance checklist	Yes	No	Measure Implemented Sign.	Measure Lifted Sign.
D-3.1 Deactivate power supply and testing EQUIPMENT_NO: NA ELECTRICIAN_NAME: NA LOTO_TAG_NO: NA	✓		Permit Issuer	
D-3.2 Is the work area barricaded for unauthorised entry		✓	Permit Issuer	
D-3.3 Is work on elevated platform if any		✓	Permit Issuer	
D-3.4 Is work platform ladder inspected and is free of defect		✓	Permit Issuer	
D-3.5 Is any portable electrical equipment required for the job if yes has it been inspected by competent person and is safe to work		✓	Permit Issuer	
D-3.6 Are workmen involved in the job informed about the risk associated with area and job	✓		Permit Issuer	
D-3.7 Is the job requiring constant supervision			Permit Issuer	
D-3.8 Is there any moving machine or movement of material handling equipment near-by	✓		Permit Issuer	
D-3.9 Are mandatory Personal protective equipment provided and used by employees on the job PPE_2: Mask PPE_3: PPE Suit PPE_4: NA PPE_1: Gloves	✓		Permit Issuer	
D-3.10 Additional PPEs recommended for job are provided	✓		Permit Issuer	
D-5.9 Is adequate illumination provided			Permit Issuer	
D-5.9.1 Other OTHER_TEXT: NA		✓	Permit Issuer	
D-8 Other units affected SAFETY_MEASURE: Na		✓	Permit Issuer	

Hazard assessment & compliance checklist	Yes	No	Measure Implemented Sign.	Measure Lifted Sign.
AFFECTED_UNITS: NA				
D-9 Safety briefing/instruction provided to persons authorised for acceptance	✓		Permit Issuer	

E - Post-work Measures required

Item	Yes	No	Answered By
E-1. All tools and garbage removed from work place and area is clean and safe for working	✓		
E-2. Other Other: cleaned	✓		

F - Approval of work permit after verification of measures

Date: _____ Signature: P Gupta

(Permit Issuer) **Permit Issuer**

G - Acceptance of Permit for work to be conducted

It is confirmed that we have reviewed the measures taken and work can be undertaken safely.

Date: _____ Name & Signature: P Gupta
