

COLD WORK PERMIT

Permit Number: PTW/CP/007

A - General Information

Permit Issuer Dept: Safety	Name: Permit Issuer
Permit Acceptor Dept: Operations	Name: Permit Acceptor
Contractor: ABC Engineering Services	Supervisor: Mukul wani

B - Work Description

Equipment Number: DC1234	Location: Plant 4
Proposed Work: Raod safety marking and electical pipeline	
Valid on Date: 2026-09-10 Time From: 17:45 Time To: 19:47	

C - Hazard Identification

Hazards from equipment/installations:

✓ Moving parts

✓ Charged surface / voltage

Hazards from work type/location:

✓ Moving Object/vehicle

✓ Underground pipe/cable

Other Hazards: -

Other Hazards in accordance with Permit No: -

D - Protective Measures - Hazard Assessment Checklist

Hazard assessment & compliance checklist	Yes	No	Measure Implemented Sign.	Measure Lifted Sign.
D-3.1 Deactivate power supply and testing		✓	Permit Issuer	
D-3.2 Is the work area barricaded for unauthorised entry		✓	Permit Issuer	
D-3.3 Is work on elevated platform if any		✓	Permit Issuer	
D-3.4 Is work platform ladder inspected and is free of defect		✓	Permit Issuer	
D-3.5 Is any portable electrical equipment required for the job if yes has it been inspected by competent person and is safe to work			Permit Issuer	
D-3.6 Are workmen involved in the job informed about the risk associated with area and job	✓		Permit Issuer	
D-3.7 Is the job requiring constant supervision	✓		Permit Issuer	
D-3.8 Is there any moving machine or movement of material handling equipment near-by	✓		Permit Issuer	
D-3.9 Are mandatory Personal protective equipment provided and used by employees on the job PPE_2: Mask PPE_1: Gloves	✓		Permit Issuer	
D-3.10 Additional PPEs recommended for job are provided			Permit Issuer	
D-5.9 Is adequate illumination provided	✓		Permit Issuer	
D-5.9.1 Other	✓		Permit Issuer	
D-8 Other units affected		✓	Permit Issuer	
D-9 Safety briefing/instruction provided to persons authorised for acceptance		✓	Permit Issuer	

Hazard assessment & compliance checklist	Yes	No	Measure Implemented Sign.	Measure Lifted Sign.

E - Post-work Measures required

Item	Yes	No	Answered By
E-1. All tools and garbage removed from work place and area is clean and safe for working	✓		Permit Issuer
E-2. Other Other: NA	✓		Permit Issuer

F - Approval of work permit after verification of measures

Date: _____	Signature: _____
_____ (Permit Issuer) Permit Issuer	

G - Acceptance of Permit for work to be conducted

It is confirmed that we have reviewed the measures taken and work can be undertaken safely.

Date: _____	Name & Signature: _____

Date: _____	Contractor Supervisor Signature: _____
