



Red holes are in identical positions on front and rear panel (looking from the front of the enclosure)