CPEN 391 Scrum Record 08 | Team 10 | Mar 9, 2021

Member	Work Done	Work In-progress	Roadblocks
Aayush Bisht	Got GPS, temperature sensor, accelerometer and camera working	 Fixing minor bugs Get heart rate sensors working 	 Burnt the temperature sensor Ridiculous amount of time for finding the first fix (GPS) RPI saving image extension issues
Shade Wong	Finished configuring Bluetooth mode and baud rate using AT commands (working on PC)	Hooking up Bluetooth chip to de1 board	BT does not receive data when connected to GPIO pins on DE1 board
Elbert Ng	Decision tree is finished	DNN training	Waiting for test data from hardware team
Andrew Shieh	WebSocket API (partially)	Fixing bugsImplement decision tree	N/A
Vincent Sastra	Setup chart widget (heart rate)Get pet API working	Poaching alert visualization	N/A