Workshop Safety Rules

Orientation, protective equipment, and first-visit requirements in the fictional shared workshop.

ORIENTATION	**Mandatory before equipment use**
FIRST VISIT	**Staff-supervised check-in**

Mandatory orientation

- All new members must attend a **60-minute general safety orientation** before entering work zones without a staff escort.
- Before operating a laser cutter, 3D printer, or power tool, members must also pass the **machine-specific induction** and have the clearance recorded in the Member Hub.
- Orientation must be refreshed every **12 months**, or earlier after a serious safety incident or major equipment change.

Protective gear and conduct

- Wear **closed-toe shoes** in all work zones. Tie back long hair, secure loose clothing, and remove dangling jewelry near moving machinery.
- Use **safety glasses, hearing protection, gloves, or respiratory protection** where posted or directed for the task. Never use gloves near rotating machinery where entanglement is possible.
- Do not bypass guards, interlocks, local ventilation, emergency stops, or manufacturer instructions. Report damaged tools, unusual smoke, and near misses to staff immediately.

Rules for first-time users

- On the first visit, check in with staff, show membership confirmation, complete the safety acknowledgment, and take a walkthrough of emergency exits and first-aid locations.
- A first-time user may only operate a machine **under direct staff supervision** until the relevant induction is signed off. Guests may observe but never operate restricted machinery.
- Equipment reservations follow limits in **Equipment Booking Guide**; booking a time slot does not grant permission to operate a machine without clearance.

Document status: Fictional example prepared solely for testing retrieval, policy comparison, and document-based question answering.