



Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Rectangles, Circles

· Features: Extrude Boss









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

· Features: Extrude Boss

HINT: Both circular bosses are the same.









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

• Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Arcs, Circles

· Features: Extrude Boss









Basic Sketch and Extrusion (Level 1)

Units: IPS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

o The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Arcs, Circles, Polygons

• Features: Extrude Boss

HINT: Use a 6-sided polygon for the blind hole.









Basic Sketch and Extrusion (Level 1)

Units: IPS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Arcs, Circles, Polygons

• Features: Extrude Boss

HINT: Use a 6-sided polygon.









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


• The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Rectangles, Circles

· Features: Extrude Boss









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 20


Design Intent:

 The part's origin location is indicated in red.

• The part is asymmetric.

All sketches are fully-defined.

- Sketch: Lines, Centerlines, Rectangles, Circles
- Features: Extrude Boss, Extrude Cut









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


• The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Rectangles

· Features: Extrude Boss









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

· Features: Extrude Boss

HINT: Corner bosses and cutouts are the same size.









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.

All sketches are fully-defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Rectangles, Circles

· Features: Extrude Boss

HINTS:

- The 25mm hole is centered on the part, and cuts all the way through the part.
- The 22mm hole is centered on the 36mm wide flange, and cuts through the part.
- Both flanges and the base are the same thickness.










Sketch Tools & End Conditions (Level 2)

- Units: MMGS
- Difficulty Level: Medium
- Certification: CSWA
- Duration (min): 10
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - All sketches are fully-defined.

- Sketch: Lines, Centerlines, Circles, Sketch Fillets
- · Features: Extrude Boss









Sketch Tools & End Conditions (Level 2)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Sketch Fillets

• Features: Extrude Boss

HINT: Edge thickness is constant.









Sketch Tools & End Conditions (Level 2)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Circles, Arcs, Offset Entities

Features: Extrude Boss









Sketch Tools & End Conditions (Level 2)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Arcs

· Features: Extrude Boss









Sketch Tools & End Conditions (Level 2)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Slots

· Features: Extrude Boss

HINT: Plane is not required. Sketch on the angled face of the extrusion.









Sketch Tools & End Conditions (Level 2)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 20

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Arcs, Slots

· Features: Extrude Boss

HINT: Use construction lines.









Sketch Tools & End Conditions (Level 2)


Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 15

Design Intent:

- The part's origin location is indicated in red.
- The part is symmetric.
- All sketches are fully-defined.

- Sketch: Lines, Centerlines, Circles, Trim, Rectangles, Slots
- Features: Extrude Boss









Sketch Tools & End Conditions (Level 2)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

The part's origin location is indicated in red.


o All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Trim, Offset Entities

· Features: Extrude Boss

HINT: Offset from outer edge.









Sketch Tools & End Conditions (Level 2)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10


Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.

All sketches are fully-defined.

- Sketch: Lines, Centerlines, Circles, Trim, Rectangles
- · Features: Extrude Boss









Sketch Tools & End Conditions (Level 2)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Circles, Arc, Sketch Fillets, Trim

· Features: Extrude Boss

HINT: Start with circles, arcs, and lines and trim.









Global Variables&Sketch Patterns (Level 3)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Circles, Centerlines, Sketch Patterns

· Features: Extrude Boss

HINT: Use a Linear Sketch pattern to create the teeth.









Global Variables&Sketch Patterns (Level 3)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

Sketch: Lines, Centerlines, Sketch Patterns

· Features: Extrude Boss

HINT: Use a Linear Sketch pattern to create the vanes.









Global Variables&Sketch Patterns (Level 3)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

Sketch: Lines, Circles, Centerlines, Arcs,
 Sketch Patterns, Sketch Fillets, Offset Entities

Features: Extrude Boss

HINT: There are 24 gear teeth.









Global Variables&Sketch Patterns (Level 3)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10


Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.

All sketches are fully-defined.

- Sketch: Lines, Circles, Centerlines, Sketch Patterns, Trim, Offset Entities, Sketch Fillets
- Features: Extrude Boss









Global Variables&Sketch Patterns (Level 3)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines, Rectangles, Sketch Patterns

· Features: Extrude Boss

HINT: Use a circular sketch pattern.









Global Variables&Sketch Patterns (Level 3)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Circles, Centerlines, Arcs, Polygons, Sketch Patterns

· Features: Extrude Boss

HINT: Use a 5-sided polygon.









Global Variables&Sketch Patterns (Level 3)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines, Rectangles, Sketch Patterns

· Features: Extrude Boss









Global Variables&Sketch Patterns (Level 3)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Circles, Polygons, Sketch Patterns

• Features: Extrude Boss

HINT: Bosses are centered on the edges.









Extrude Cut & Fillet/Chamfer (Level 4)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

Features: Extrude Boss, Extrude Cut, Fillets and Chamfers

HINT: Use the Polygon tool to create hex.









Extrude Cut & Fillet/Chamfer (Level 4)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15


Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.

All sketches are fully-defined.

- Sketch: Lines, Centerlines, Circles, Arc, Sketch Fillets
- Features: Extrude Boss, Extrude Cut









Extrude Cut & Fillet/Chamfer (Level 4)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.


• The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Arcs

Features: Extrude Boss, Extrude Cut, Fillets and Chamfers









Extrude Cut & Fillet/Chamfer (Level 4)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15


Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

- Sketch: Lines, Centerlines, Circles, Arcs
- Features: Extrude Boss, Extrude Cut, Fillets and Chamfers










Extrude Cut & Fillet/Chamfer (Level 4)

- Units: MMGS
- Difficulty Level: Medium
- Certification: CSWA
- Duration (min): 20
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - All sketches are fully-defined.

- Sketch: Lines, Centerlines, Circles
- Features: Extrude Boss, Extrude Cut, Fillets and Chamfers









Extrude Cut & Fillet/Chamfer (Level 4)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 35


Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

- Sketch: Lines, Centerlines, Circles, Sketch Fillets
- Features: Extrude Boss, Extrude Cut










Extrude Cut & Fillet/Chamfer (Level 4)

- Units: MMGS
- Difficulty Level: MediumCertification: CSWA
- Duration (min): 25
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - o All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Rectangles
- Features: Extrude Boss, Extrude Cut, Fillets and Chamfers

HINT: Start with a rectangle, placing the lower right corner at the origin.









Extrude Cut & Fillet/Chamfer (Level 4)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

 Features: Extrude Boss, Extrude Cut, Fillets and Chamfers

HINT: The rib is centered on the lower circular holes.









Extrude Cut & Fillet/Chamfer (Level 4)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.


o The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

• Features: Extrude Boss, Extrude Cut









Extrude Cut & Fillet/Chamfer (Level 4)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


o All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Arcs

• Features: Extrude Boss, Extrude Cut

HINT: Create all 8 holes in a single feature.









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: Medium
 Certification: CSWA
 Duration (min): 10

Design Intent:

 The part's origin location is indicated in red.


o The part is asymmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Circles, Sketch Patterns

• Features: Extrude Boss









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

· Features: Extrude Boss

Reference Geometry: Planes

HINT: Start ribs inside cylinder wall.









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


o The part is asymmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Rectangles, Arcs, Circles, Slots

• Features: Extrude Boss









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.


o The part is asymmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Arcs, Circles, Sketch Fillets

• Features: Extrude Boss









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 35

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

Features: Extrude Boss, Extrude Cut, Fillets and Chamfers









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWA

• Duration (min): 20

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

o All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Trim

• Features: Extrude Boss, Extrude Cut









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

• Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.

All sketches are fully-defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Trim

• Features: Extrude Boss, Extrude Cut

· Reference Geometry: Planes

HINT: Use a sketch to define the plane.









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

• The part is asymmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features


• Sketch: Lines, Centerlines, Circles

• Features: Extrude Boss, Extrude Cut

· Reference Geometry: Planes, Axes

HINTS:

- Create an axis using a standard plane.
- Use Up to Surface end conditions.









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

o All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Sketch Fillets, Convert Entities, Trim
- Features: Extrude Boss, Extrude Cut
- Reference Geometry: Planes

HINT: The pipe is tangent to the plate.









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10


Design Intent:

- The part's origin location is indicated in red.
- The part is symmetric.
- o All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Rectangles, Arcs, Circles
- Features: Extrude Boss, Extrude Cut
- · Reference Geometry: Planes

HINT: Create a plane on an angle through the front edge, and cut with a circle.









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Arcs

· Features: Revolves

HINT: This can be built using a single feature.









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:


 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles
- Features: Revolves, Extrude Boss, Fillets and Chamfers









Revolve Boss/Cut (Level 6)


Units: MMGS

Difficulty Level: Easy
 Certification: CSWA
 Duration (min): 5

- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Arcs, Polygons
- Features: Revolves, Extrude Boss, Fillets and Chamfers
- · Reference Geometry: Planes









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:


 The part's origin location is indicated in red.

o The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Arcs
- Features: Revolves, Extrude Boss, Fillets and Chamfers









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Arcs

• Features: Revolves, Extrude Boss

HINT: Cut with a revolve feature.









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines

· Features: Revolves









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.


• The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Trim, Slots, Offset Entities
- Features: Revolves, Extrude Boss, Extrude

HINT: Slot is dimensioned to the overall width.









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


• The part is asymmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Trim, Sketch Fillets, Offset Entities
- Features: Revolves, Extrude Boss, Extrude

HINT: The "U" boss is tangent to the through hole and passes through the Origin.









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Trim

• Features: Revolves, Extrude Cut

HINT: Start with a full revolve feature.









Revolve Boss/Cut (Level 6)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

o All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Trim, Arcs
- Features: Revolves, Extrude Boss, Extrude
 Cut

HINT: Bosses then cuts.









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

Sketch: Lines, Circles, CenterlinesFeatures: Revolves, Extrude Cut

Patterns: Circular










Feature Patterning (Level 7)

- Units: MMGS
- Difficulty Level: MediumCertification: CSWA
- Duration (min): 10
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is asymmetric.
 - All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Circles, Centerlines
- Features: Extrude Boss, Revolves, Fillets and Chamfers
- Patterns: Linear
- · Reference Geometry: Planes

HINT: Skip instances in the Linear Pattern.









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


o The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

Sketch: Lines, Arcs, CenterlinesFeatures: Extrude Boss, Revolves

Patterns: Linear









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines, Arcs

Features: RevolvesPatterns: Circular









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

o The part is axisymmetric.

o All sketches are fully-defined.

Suggested Sketch Tools / Features


• Sketch: Lines, Circles, Centerlines, Rectangles

Features: Extrude Boss, Extrude Cut

Patterns: Circular, Mirror

Reference Geometry: Planes

HINT: The holes and cuts are patterned.









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15


Design Intent:

- The part's origin location is indicated in red.
- The part is symmetric.
- All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Circles, Rectangles, Offset, Slots, Centerlines
- Features: Extrude Boss, Extrude Cut, Fillets and Chamfers
- Patterns: Linear

HINT: Thickness remains the same.









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 30

Design Intent:

 The part's origin location is indicated in red.

The part is axisymmetric.

All sketches are fully-defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines

Features: Extrude Boss, Revolves, Fillets and Chamfers

· Patterns: Circular

HINT: All 4 blades are evenly spaced.









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 25

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines, Slots

• Features: Extrude Boss, Extrude Cut

Patterns: Linear, Mirror









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 35

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines, Rectangles

Features: Extrude Boss, Extrude Cut, Fillets and Chamfers

· Patterns: Mirror









Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 45

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines, ARcs

 Features: Extrude Boss, Extrude Cut, Revolves, Fillets and Chamfers

Patterns: Mirror









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Circles, Centerlines, Polygons, Sketch Fillets

· Features: Sweeps









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

• Design Intent:

 The part's origin location is indicated in red.


o The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Circles, Centerlines, Sketch Fillets

• Features: Sweeps









Sweep Boss/Cut (Level 8)

Units: IPS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Circles, Centerlines, Arcs
- Features: Revolves, Sweeps, Fillets and Chamfers

HINT: Extend sweep into sphere.









Sweep Boss/Cut (Level 8)

Units: IPS

Difficulty Level: MediumCertification: CSWA

Duration (min): 20Design Intent:

 The part's origin location is indicated in red.


o The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

Sketch: Lines, Circles, CenterlinesFeatures: Sweeps, Extrude Cut

Patterns: Mirror









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: HardCertification: CSWA

• Duration (min): 40

Design Intent:

 The part's origin location is indicated in red.

• The part is asymmetric.

All sketches are fully defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines

• Features: Lofts, Extrude Boss, Extrude Cut

Patterns: Circular

HINT: The loft is between two circles.









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: EasyCertification: CSWA

Duration (min): 5

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


o All sketches are fully defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Arcs

· Features: Sweeps

HINT: The Sweep can use the Circular Profile option.









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 20

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Arcs, Centerlines, Slots, Trim

Features: Extrude Boss, Sweeps, Fillets and Chamfers

Patterns: Mirror










Sweep Boss/Cut (Level 8)

- Units: MMGS
- Difficulty Level: EasyCertification: CSWA
- Duration (min): 10
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - All sketches are fully defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Circles, Centerlines, Arcs, Rectangles, Sketch Fillets
- Features: Lofts, Extrude Boss, Extrude Cut
- Reference Geometry: Planes

HINT: Loft between a square sketch and a planar face.









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: Medium
 Certification: CSWA

Duration (min): 10

• Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines

• Features: Lofts, Extrude Boss, Extrude Cut

Reference Geometry: Planes

HINT: The cap is lofted.









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.

o All sketches are fully-defined.

o All fillets on the path are equal.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

• Features: Sweeps

