Hampton & Bayside Leadlight Co.

9 Sybil St. Hampton East, 3188 VIC E <u>Leighschellekens@yahoo.com.au</u> M 0407 858 453



ABN 94412939953

TAX INVOICE

27 February 2020

Attention: Phillip Bellifemine phillipb@aapt.net.au 0414244267

RE: 3 Kalymna Grove, St Kilda East Unit 1

Description: Onsite repair of front door leadlight, one broken clear flemish glass

Quote number: 27042001

DESCRIPTION	QUANTITY	UNIT PRICE	COST	
onsite repair	I	\$ 200.00	\$	200.00
		Subtotal	\$	200.00
		plus GST	\$	20.00
		TOTAL	\$ 2	20.00

Bank Details:

Name: Hampton & Bayside Leadlight

Acc: 02206946

Bank: Qantas Credit Union

BSB: 704865

Remittance advice: Payment is due upon receipt of goods or services