Complete this lab as follows:

- 1. Insert the PCI adapter into the motherboard.
 - 1. Above the computer, select **Motherboard** to switch to the motherboard view of the computer.
 - 2. Under Shelf, expand **Network Adapters**.
 - 3. Drag the **Network Adapter**, **Ethernet 10/100/1000BaseTX**, **PCIe** card to a free PCIe slot on the computer's motherboard.



- 2. Move the Ethernet cable from the computer's built-in network adapter to the new PCIe network card.
 - 1. Above the computer, select **Back** to switch to the back view of the computer.
 - 2. Drag the *Ethernet cable* from the built-in port to the port on the PCle network adapter.
- 3. Confirm that the computer is connected to the local network and the internet.
 - 1. Above the computer, select **Front** to switch to the front view of the computer.
 - 2. Select the *power button* on the computer case to turn on the computer. Wait for the operating system to load.
 - 3. Right-click Start and then select Terminal (Admin).
 - 4. From the PowerShell prompt, type **ping 192.168.0.10** and then press **Enter** to test connectivity to the local network server.
 - 5. From the PowerShell prompt, type **ping 198.28.2.254** and then press **Enter** to test connectivity to the internet.