

XR200 Device Setup

The XR200 device is powered on by holding the side button for three seconds. The status light turns blue when the device is ready to use.

XR200 Troubleshooting

If the device does not power on, charge it for at least one hour using the included USB-C cable. Contact support if the issue persists after charging.