```
M22
                                                                                       —( M20 )
                         1/1
                                       DPLSY
                                                                                Y3
                                               K1000
                                                               D3
T1
                                                                                       —( M11 )
X20
                                       DPLSY
                                               K1000
                                                               D0
                                                                                Y0
X20
                                                                                        —( Y24 )
M1
                                                                       TMR
                                                                                T1
                                                                                        K600
         <del>1</del>/|-
X20
                                                                        CNT
                                                                                        K22
                                                                        CNT
                                                                                СЗ
                                                                                        K10000
C1
        X20
                                                                       CNT
                                                                               C2
                                                                                        K5
C2
         Y23
         1/
                                                                                        -( Y22 )
+
                                                                                        —( M12 )
M12
         T2
M12
                                                                                        —( Y23 )
M12
                                                                       TMR
                                                                               T2
                                                                                        K20
Y23
                                                                                RST
                                                                                        C2
T2
                                                                                RST
                                                                                        M12
Y23
                                                                                       —( M14 )
M14
+
M14
                                       DPLSY
                                               K1000
                                                               D1
+
                                                                               Y1
M21
X21
                                                                                        —( M15 )
M15
                                                                                RST
                                                                                        M14
X21
                                                                                        —( M16 )
M16
                                                                        CNT
                                                                               C8
                                                                                        K5
                                                                                        —( M4 )
M4
                                       DPLSY
                                                               D2
                                                                                Y2
                                               K1000
M7
1 |
M8
+
М9
+
+
M19
M7
                                                                               ____( Y5 )
```

```
RST
                                                                                   M4
                                                                            RST
                                                                                   C8
                                                                                   —( M23 )
M23
4 +
M23
                                                                    TMR
                                                                           T8
                                                                                   K50
Т8
                                                                                    —( M7
        1/
                                                                                   —( Y25 )
Y25
X25
                                                                                   —( M17 )
M17
                                                                            RST
                                                                                   M7
X25
                                                                                   —( M20 )
M17
                                                                    TMR
                                                                            T7
                                                                                    K300
T7
M20
                                                                                    -( M21 )
X24
                                                                            RST
                                                                                    M20
                                                                            RST
                                                                                   M21
                                                                            C7
                                                                                    K2
C7
                                                                            RST
                                                                                    M6
                                                                            RST
                                                                                   M8
                                                                            RST
                                                                                    T7
                                                                            RST
                                                                                    M23
                                                                            RST
                                                                                    Т8
                                                                            RST
                                                                                    M17
C7
М9
                                                                    TMR
                                                                            T5
                                                                                    K300
T5
                                                                            RST
                                                                                    M9
                                                                            RST
                                                                                    C7
```

C	RST
K6	C5
K10	O6
MO	RST
M1	RST
M2	RST
М3	RST
M4	RST
ı	RST
	RST
	RST
ı	RST
М	RST
M	RST
M	RST
N	RST
N	RST
	RST
	RST
ı	RST
M	RST
N	RST
N	RST
M	RST
М	RST
N	RST
N	RST
T	RST
	RST
Т	RST
T	RST
T	RST
1	RST

