1.0 PURPOSE: To describe the procedure for ongoing identification of hazards, the assessment of risks and implementation of necessary control measures.

#

- **2.0 SCOPE**: This procedure is applicable to all activities, personnel including sub-contractors and visitors, and facilities at SHAKTI PUMPS (INDIA) LIMITED, PITHAMPUR DIST. DHAR.
- 2.0 REFERENCE: #SO 45001:2018 Occupational Health and Safety Management System.
- **3.0 RESPONSIBILITY**: All HOD's are responsible for identification and updating of hazards, assessment of risk and the implementation of control measures in their work areas.

#

5.0 REQUIREMENTS:

- 5.1 Feedback from employees
- 5.2 Legal Requirements
- 5.3 Formation of core committee
- 5.4 Process Knowledge

#

6.0 PROCEDURE:

- 6.1 Hazard identification and risk assessment is carried out by concerned HOD as proactive measure through
 - On site visits.
 - Occupational Health and safety legal and other requirements.
 - Record of accidents and incidents.
 - Communication from Employees and other interested parties.
- 6.2 Identification of hazards and assessment of risk shall include the following
 - Routine and Non-Routine activities (Including Sub Contractors and Visitors)
 - Activity of personnel having access to the work place.
 - Facilities at workplace, whether provided by organization or others.
- 6.3 Identification of hazards and evaluation of risk shall be documented in Format. No. QF-MR-08.
- 6.4 Risk is determined without controls and with control measures in place for identified hazards by estimating the potential severity of consequences of injury and probability of occurrences.
- 6.5 **Severity:** What is the worst injury that could result from the hazard?

Severity of consequence of injury is classified into three categories, that is low, Medium and high.

Low:- Leading to temporary discomfort or first aid cases.

Medium:- Requiring medical attention / hospitalization, loss of man days and medical compensations.

High:- Leading to permanent disability, disorder or legal violation.

#

6.6 Probability of Occurrence: - How likely is that these circumstances can and will lead to incident / accident (Actual / Potential). Probability of occurrences is classified into three categories i.e. Low, medium and high.

Low: - Rare chances (<10%) or never happened.

Medium: - Can happen (<50% but >10%) or has happened.

High:- More than 50% chances or will happen.

6.7 Risk Level is evaluated based on following evaluation criteria of probability of occurrence and potential severity of harm.

EVALUATION CRITERIA

Severity → Probability ↓	Low	Medium	High
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Extreme

6.8 For Risk levels evaluated above, their control action plan is as follows.

#

Trivial - 1	No Action is required and no documentary record to be kept.
Tolerable - 2	No additional controls are required. Monitoring is required to ensure that controls are maintained.
Moderate - 3	Risk falling in to this category shall be made to reduce by applying additional controls.
Substantial - 4	Risk requiring remedial actions shall be reduced as soon as possible by taking objectives.
Extreme - 5	Risk for which operation should be stopped till corrective action to reduce risk is completed.

6.9 Hazard identification and risk assessment shall be review comprehensively once in a year or in case of any change in process, product or facilities by department HOD.

7.0 MONITORING / MEASUREMENT:##

- 7.1 Number of accidents, incident and near miss
- 7.2 Number of revisions in HIRA document.

8.0 RECORDS:

8.1 #Hazard identification and risk assessment Format.

QF-MR-08