


Fracking: Pros, Cons, Uncertainty, and Protecting the Safety of Frostburg's Drinking Water



Mountain Ridge
Environmental Science Students






Student calibrating the YSI Pro30



Tributary T1





The tag line is installed



pH was measured using a YSI pH10 Meter



Student records data onto data sheet



YSI ProODO measures dissolved oxygen



YSI Pro30 measures the specific conductivity






Turbidity being measured using a Hach Turbidimeter



She fills up one bottle



She dumps the water out downstream



The water samples are put on ice



At the Aquifer and Frostburg Reservoir, the water must be pulled and tested from buckets



Frostburg's Water Treatment Plant



For treatment raw and treatment mixed, the water was pulled and tested from faucets

The bottle samples from the streams are shipped on ice with a chain of custody form via FedEx



Summit Environmental Technologies, Inc.

3310 Win Street

Cuyahoga Falls, Ohio 44223

Tel: 330.253.8211 Fax: 330.253.4489

Analysis Request/

For Summit Environmental

Order ID: 1227005

COG

Company Name (Please Print) MRHS		Project Name				Order ID: 1227005		Page _____							
Company Address <i>100 Grasmick Lane Frostburg, MD 21532</i>		Project Address						COC							
Client Phone No. <i>301-689-3377</i>		Report to <i>Tom Kozikowski</i>													
Client Fax No. <input checked="" type="checkbox"/> Please Fax Results <input type="checkbox"/>		PO#													
Client Email <input checked="" type="checkbox"/> Please Email Results <input type="checkbox"/>		Quote No.													
Contact Person															
Sampled by <i>Tom Kozikowski</i>		Check if Ohio VAP samples <input checked="" type="checkbox"/>													
#	Sample Identification		Date Collected	Time Collected	Grab	Composite	Matrix: S=Solid, L=Liquid, O=Oil SL=Sludge, A=Air, DW=Drinking Water	Preservative	Number of Containers	<i>gross alpha beta</i>	<i>Br⁻, Cl⁻, SO₄⁻²</i>	<i>Ba, Sr, Al, Ca, Fe, Mn, Mg</i>	<i>Na, pH</i>	<i>ALK, ACID</i>	<i>methane</i>
<i>Please Check Analytical Box</i>															
	Tributary T1	11-8	11:15	X	DW	None	7	X	X	X	X	X	X	X	
	Tributary C6	11-8	11:40	X	DW	None	7	X	X	X	X	X	X	X	
	Tributary B7	11-8	10:47	X	DW	None	7	X	X	X	X	X	X	X	
	Tributary G8	11-8	10:01	X	DW	None	7	X	X	X	X	X	X	X	
<i>1227005-01-04</i>															

Relinquished by:	Date	Time	Received by:	Date	Time
<i>Jean R. Young</i>	11-8-12	1:30 pm			
Received in lab by:	Date	Time	Rush Requested By:	Must be approved by lab manager	
<i>Jean R. Young</i>	11-8-12	10:00 am		Date	

White and yellow pages should accompany samples to the laboratory.

Notes/Comments:

Analyze all at ppb.

Detection limit 10 ppb



The information is inputted into our baseline water quality excel data files and then proofread independently three times.



Rock with HOBO monitor is pulled from stream



Data is collected off of the HOBO monitors






**The information...is transferred to the computer via USB cord
The newly obtained data is then plotted and analyzed**

Our Data


Barium and Strontium Levels in Tributary T1 February 2012–February 2013

Plotted with the Depth on a Staff Plate



Barium and Strontium Levels in Tributary T1 February 2012–February 2013

Plotted with the Depth on a Staff Plate



Barium (ppb) Schijf
Strontium (ppb) Schijf
Depth at Staff Plate (cm)



Strontium
Average: 42 ppb

Barium
Average: 33 ppb

Feb 2012 March April May June July Aug Sept Oct Nov Dec Jan Feb 2013

Sampling Month

Concentration (ppb) or Depth in Centimeters

80

70

60

50


40

30


20

Barium and Strontium Levels in Tributary T1 February 2012–February 2013


Plotted with the Depth on a Staff Plate




**Barium and Strontium Levels in Tributary B7 September 2012 - February 2013
plotted with Depth on Staff Plate**




Barium and Strontium in G8 from September 2012-February 2013 plotted with depth at staff plate




Barium and Strontium at Tributary C6 from Februry 2012-Februry 2013 Plotted with Depth at the Staff Plate




**Barium and Strontium Levels in Tributary T1 February 2012-February 2013
Plotted with the Depth on a Staff Plate**




Barium and Strontium Levels in Treatment Mixed February 2012-February 2013 Plotted with the Depth on a Staff Plate




Barium and Strontium Levels in Treatment Raw February 2012-February 2013 Plotted with Depth on Staff Plate



Barium and Strontium at the Frostburg Reservoir from February 2012 to December 2012 plotted with Staff Plate Depth




Barium and Strontium Levels in Aquifer February 2012-February 2013 Plotted with Depth on a Staff Plate







Specific Conductivity in Tributary T1 from June 2012-February 2013 Plotted with Depth on a Staff Plate




Specific Conductivity at B7 from September 2012-Feburary 2013 Plotted with Depth at Staff Gauge




Specific Conductivity in G8 from September 2012- January 2013




Specific Conductivity in Tributary C6 from June 2012 - February 2013
Plotted with Depth at Staff Gauge




Specific Conductivity in Tributary T1 from June 2012-February 2013
Plotted with Depth on a Staff Plate




Specific Conductivity in Treatment Mixed from June 2012-Feburary 2013 Plotted with Depth on a Staff Plate




Specific Conductivity for Treatment Raw from June 2012-February 2013
Plotted with Depth at Staff Gauge at T1



Specific Conductivity in Frostburg Reservoir from May 2012-January 2013
Plotted with Depth at Staff Gauge




Specific Conductivity in Aquifer from June 2012-Feburary 2013 Plotted with Depth on a Staff Plate




Chloride, Sodium, Calcium, & Magnesium Levels in Tributary T1


September 2012-February 2013 Plotted with Depth at the Staff Plate




Chloride, Sodium, Calcium & Magnesium Levels in Treatment Mixed
September 2012-February 2013 Plotted with Depth at Staff Plate




Chloride, Sodium, Calcium and Magnesium at Treatment Raw
September 2012-February 2013 Plotted With Depth At Stream Plate



Chloride, Sodium, Calcium, & Magnesium at the Frostburg Reservoir from September 2012-February 2013 Plotted with Depth at the Staff Gauge




Chloride, Sodium, Calcium & Magnesium Levels in Aquifer




**COMPARING OUR
BASELINE DATA
TO
FRACKING FLUID**

Chloride Concentrations at all 8 testing sites Sept 2012-Feb 2013




Chloride Concentrations at all 8 testing sites Sept 2012-Feb 2013

Pure Frack Fluid also shown




Chloride Concentrations at all 8 testing sites Sept 2012-Feb 2013


1:100 Diluted Frack Fluid also shown




Strontium Concentrations at all 8 Testing Sites Feb 2012-Feb 2013



Strontium Concentrations at all 8 Testing Sites Feb 2012-Feb 2013 with Pure Frack Fluid



Strontium Concentrations at all 8 Testing Sites Sept 2012-Feb 2013 with 1:1000 Diluted Frack Fluid




Other Key Fracking Indicators that We Are Monitoring...



Analyte	Average Concentration in Tributary T1	Concentration in Frack Fluid	Multiple of Natural Level to Frack Fluid
Bromide	Below 10 ppb	445,000 ppb ¹	45,000 times
Barium	33ppb	686,000ppb ¹	21,000 times
Strontium	45ppb	1,000,000ppb ¹	20,000 times
Sp. Conductivity	125 uS/cm	700,000 uS/cm	5600 times
Gross-Alpha	3.92 pCi/L	1750 pCi/L ²	450 times
Gross-Beta	5.34 pCi/L	760 pCi/L ²	140 times
Iron	942 ppb	39000ppb ¹	40 times
Aluminum	4707 ppb	39,000 ppb ¹	8 times
Manganese	672 ppb	2630ppb ¹	4 times

¹- The Center for Rural Pennsylvania, The Impact of Marcellus, 2011

²- EPA- <http://www.epa.gov/hfstudy/comparisonofhffluidscompositionwithproducedformationwater.pdf>

10229796 Tributary T1







What might a contamination event look like if frack fluid is diluted 1:1000?
(peak is 700 us/cm)(made to scale)

Pure Frack Fluid = 700,000 us/cm

Hopefully, a contamination event like this is never observed and citizens can continue to confidently drink from the municipal water supply.





It is our hope to provide quarterly notifications indicating that the water is “still safe” to drink.

Inform the Frostburg Water Treatment Plant.



Proceed to take more detailed samples with our 20 other analytes to verify whether or not fracking was in fact the cause of the event.

We would request that a government agency would assist in further analysis, monitoring, and resolution of the issue.

