FixPoint Repair

REPAIR ESTIMATE

Date: 2025-12-11

Customer: Rowan Brannigan

Device: Kestrel Air 2

IMEI: 69 606539 537328 7

Diagnosis: Cracked display, touch unresponsive in lower third

Charge port flex	USD 52.00
Logic board rework	USD 161.00
Battery	USD 82.00
Parts total	USD 295.00
Labor (2.5 hrs)	USD 225.00
ESTIMATE TOTAL	USD 520.00

Estimate valid 30 days. Diagnostic fee waived if repair is approved.