Circuit Doctor

REPAIR ESTIMATE Date: 03/24/2025

Customer: Sage Tamura
Device: Halcyon Fold 3
Serial No.: B9CKRSN42H2W

Diagnosis: Cracked display, touch unresponsive in lower third

Display assembly		$202.00
Charge port flex		$51.00
Battery		$69.00
	Parts total	$322.00
	Labor (4.0 hrs)	$360.00
	ESTIMATE TOTAL	$682.00

Estimate valid 30 days. Diagnostic fee waived if repair is approved.