Circuit Doctor

REPAIR ESTIMATE Date: 4 June 2025

Customer: Avery Tamura
Device: Arcway Phone 12
IMEI: 64 242702 669081 7

Diagnosis: Liquid damage to charging port

Battery		$81.00
Display assembly		$236.00
	Parts total	$317.00
	Labor (3.0 hrs)	$390.00
	ESTIMATE TOTAL	$707.00

Estimate valid 30 days. Diagnostic fee waived if repair is approved.