
V16 contact / whole COM diagnostics, environment 0; foot points are approximations
Foot count
scheduled stance
foot net normal force >20 N
Whole COM / target [m]
whole COM x
target x
smooth reference x
whole COM y
target y
smooth reference y
Signed margin [m]
next 3-foot support triangle margin [m]
liftoff margin gate
Time [s]