Complika Sonalika

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

										PRI	NT		
COUNTRY NAME	BANGLADESH			DBR NAME			ACI LTD		DBR C	DBR CODE		2700036	
DEALER NAME	ACI JESSORE JESSORE		DEALER A			DRESS Jessore		CUST	CUSTOMER NAME		Md. Amir Ali Sarder (Gopalgonj)		
CUSTOMER ADDRESS												(copalgorij)	
Warranty Claim No	2700036-94	76B9-2023-7		JobCard N	No		2700036-94	76B9-2023-75	Chassis No		EXC	DJ1194048S3	
Tractor Model	ALL ROUNDER 55 SUPREME			Engine No			4100FL04C919053			Job Card Date		eb-2023	
Date Date of Sale	09-Feb-2023 10-Sep-2022			Last Service Date Hours Worked			349.00			Date of Failure Invoice No		09-Feb-2023 3602811436	
Last Service Hours	10-06р-202	•		Customer		aint		OULD NOT START			3002	011430	
Invoice Date	28-Jul-2022			Buyer Ref No									
EDI & Contos Dataila	***************************************											Mark the Company of t	
PDI & Service Details PDI	1st Service	2nd Service	3rd	Service		4th Serv	ice	5th Service	6th Sen	vice	7th Se	rvice	
08-Aug-2022		Zila Gel Vice	Jiu	OCIVICO		401 Jei V	100	Stil Service	our our	1100	7111 001	VICE	
							-						
Complaint Details													
Data not available.													
Part Details											***************************************	······································	
Complaint Code Failure Type CULPRIT PART NO			Part No 10029943BD STAI			Part Description		Quantity	Billing Type WARRANTY		SE	Analysis	
Labour Detail(B)	COLPRITEAR	TNO	10029943	360	SIARI	ER SWI	ICH	1.00	IVARRAN	IY			
Complaint Code Action Taken				Labour Code				Lat		Labour Charge			
Data not available.													
Consumables C													
Complaint Code Description				Qty				Rate	Rate Amount			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Data not available.													
OutsideJob (D)													
Complaint Code	de Details of Job			BillNo			illNo	Date		An	Amount		
Data not available.													
Claim Summary													
Part(A)	Labour (Consur						
Outside Job (D)			Sale Tax (E) 0				Total(A+B+C+D+E)			22850			
Culprit Part No	10029943	BD		Culorit	Part N	ame							
Dealer Analysis	AFTER INSPECTION WE FOUND THAT STARTER SWITCH DEFECTIVE.				Dealer Action Taken				Complaint status Close				
					-								

