

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala, Jalandhar Road, Hoshiarpur

Warranty Claim

PRINT BANGLADESH DBR NAME ACILTD DBR CODE 2700036 COUNTRY NAME DEALER ADDRESS DHAKA ACI DHAKA DHAKA CUSTOMER NAME Supna DEALER NAME CUSTOMER ADDRESS 2700036-9476B2-2022-47 JobCard No 2700036-9476B2-2023-13 Chassis No JYASR1088709S3 Warranty Claim No 3100FL14H1084603 Job Card Date **DI 35 RX 2WD** Engine No 26-Jun-2022 Tractor Model Last Service Date Date of Failure 26-Jun-2022 26-Jun-2022 Date Invoice No 3602802808 423 00 Date of Sale 30-Nov-2021 Hours Worked BAD NOISE WAS COMING Customer Complaint Last Service Hours FROM THE REAR AXLE. Buyer Ref No Invoice Date 14-Aug-2021 PDI & Service Details 7th Service PDI 1st Service 6th Service 2nd Service 3rd Service 4th Service 5th Service 23-Aug-2021 Complaint Details Data not available. Part Details Complaint Code Part No Quantity Billing Type SE Analysis Failure Type Part Description CULPRIT PART NO 10007294AC COVER (FOR TRUMPET HSG.) WARRANTY CULPRIT PART NO 20003761AA TAPPER ROLLER BEARING 3982/3920 WARRANTY Labour Detail(B) **Complaint Code** Action Taken Labour Code Labour Hours Labour Charge Data not available. Consumables C Complaint Code Description Qty Rate Amount Data not available OutsideJob (D) Complaint Code Details of Job BillNo Date Amount Data not available Claim Summary Part(A) Labour (B) Consumables (C) Outside Job (D) 0 Sale Tax (E) Total(A+B+C+D+E) 22850 Culprit Part No 20003761AA Culprit Part Name AFTER INSPECTION WE FOUND Dealer Analysis THAT TAPPER ROLLER BEARING Dealer Action Taken Complaint status Close HAS BROKEN. VENDOR ORBIT



