

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

PRINT 2700036 DBR CODE ACI LTD DBR NAME BANGLADESH Md. Rasel CUSTOMER NAME COUNTRY NAME DEALER ADDRESS DHAKA ACI DHAKA DHAKA DEALER NAME CUSTOMER ADDRESS BYASR1019388S3 Chassis No 2700036-9476B2-2023-23 JobCard No 2700036-9476B2-2022-57 10-Sep-2022 Job Card Date Warranty Claim No 3100FL14A1015348 **Engine No DI 35 RX 2WD** 10-Sep-2022 Date of Failure Last Service Date Tractor Model 3602811434 10-Sep-2022 Invoice No 1210.00 Date **Hours Worked** 29-Jun-2021 FRONT AXLE BKT HAS Date of Sale **Customer Complaint** CRACKED. Last Service Hours Buyer Ref No 29-Jan-2021 Invoice Date 7th Service 6th Service PDI & Service Details 5th Service 4th Service 3rd Service 2nd Service 1st Service PDI 09-Feb-2021 Complaint Details Complaint Desc Complaint Code FRONT AXLE -SUPPORT BROKEN Sub Aggregates Aggregates FA16 FRONT AXLE Part Details SE Analysis **Billing Type** Quantity Part Description Part No Failure Type Complaint Code WARRANTY 1.00 INTEGRAL FRONT AXLE BKT 10070250EA CULPRIT PART NO Labour Detail(B) **Labour Charge Labour Hours** Labour Code **Action Taken Complaint Code** Data not available. Consumables C Amount Rate Qty Description Complaint Code Data not available. OutsideJob (D) Date Amount BillNo Details of Job Complaint Code Data not available. Claim Summary Consumables (C) Labour (B) Part(A) 22850 Total(A+B+C+D+E) 0 Sale Tax (E) Outside Job (D) 10070250EA **Culprit Part Name** Culprit Part No AFTER INSPECTION WE FOUND Complaint status Close CRACK MARK ON INTEGRAL FRONT AXLE BKT. Dealer Action Taken Dealer Analysis FABRICATED Remarks Acknowledgement Date 15-Sep-2022 Acknowledgement FRONT AXLE BRACKET WELDING JOINT GOT CRACKED DUE TO

