

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala, Jalandhar Road, Hoshiarpur

Warranty Claim

PRINT 2700036 DBR CODE ACI LTD DBR NAME BANGLADESH Md. Abdus COUNTRY NAME Sattar Amchottar, Nawdapara, City CUSTOMER NAME ACI MOTORS - RAJSHAHI DEALER ADDRESS Hat Road, Rajshahi, Pramanik DEALER NAME CUSTOMER ADDRESS CZDDR1129007S3 Chassis No 2700036-9476B3-2023-100 JobCard No 2700036-9476B3-2022-153 22-Jul-2022 Job Card Date Warranty Claim No 4100FL14K1124472 60 RX SUPREME 2WD Engine No 22-Jul-2022 Date of Failure Tractor Model Last Service Date 3602805605 22-Jul-2022 Invoice No Date 441.00 Hours Worked 06-Mar-2022 EXHAUST SMOKE WAS COMING FROM THE EXHAUST FLANGE Date of Sale Customer Complaint Last Service Hours Buyer Ref No 25-Nov-2021 Invoice Date DI & Service Details 7th Service 6th Service 5th Service 4th Service 2nd Service 3rd Service 1st Service PDI 07-Dec-2021 complaint Details SHEET-MUFFLER PIPE FLANGE WELDING Sub Aggregat JOINT OPENED SM29 VEHICLE Part Details Billing Type Quantity Part Description Failure Type WARRANTY EXHAUST FLANGE 4cyl. (Rx.) 700405245C CULPRIT PART NO Labour Detail(B) Labour Charge Labour Hours Labour Code **Action Taken** Complaint Code Data not available. Consumables C Rate Amount Qty Complaint Code Description Data not available. OutsideJob (D) Date Amount BillNo Details of Job Complaint Code Data not available. Claim Summary Consumables (C) Labour (B) Part(A) Total(A+B+C+D+E) 22850 Sale Tax (E) 0 Outside Job (D) Culprit Part Name 700405245C Culprit Part No AFTER INSPECTION WE FOUND Complaint status Close THAT EXHAUST FLANGE HAS Dealer Action Taken Dealer Analysis LEAKAGE BLOW 29-Jul-2022 Remarks ED HOLE Acknowledgement Date Acknowledgement OBSERVED DIPTENDU ROY Acknowledge Done By

