SONALIKA

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

						,							,
											PRI	NT	
COUNTRY NAME	BANGLADESH			DBR NAME			ACI LTD			DBR CODE			2700036 Md. Mandar
DEALER NAME .	ACI JESSORE JESSORE			DEALER ADDRESS			Jessore			CUSTOMER NAME			Ali (Chuadanga)
CUSTOMER ADDRESS	3												
Warranty Claim No	2700036-9	476B6-2023-	-10	Jo	obCard No		2700036-94	76B6-2023	-56 Ch	nassis No		AZD	DJ1138330S3
Tractor Model	60 RX SUPREME 2WD			Engine No			4100FL24C1150183		Jo	Job Card Date		16-Jan-2023	
Date	16-Jan-2023 09-Jun-2022			Last Service Date						ate of Failure			an-2023
Date of Sale	09-Jun-20	22			ours Worked		597.00	WAS CON		voice No		3602	808759
Last Service Hours	29-Mar-2022				Customer Complaint			BAD NOISE WAS COMING FROM THE SILENCER.					
Invoice Date	29-War-20			В	uyer Ref No	1							
PDI & Service Details	1st Service	2nd Service	.	and Com		44h C		Fat Consta		Cab Caralas		741.0	
12-Apr-2022	13t SELVICE	Zild Service		3rd Sen	rice	th Serv		5th Service		6th Service		7th Se	TVICE
12-Apr-2022				-						-			
Complaint Details		31											
Data not available.													
Part Details													
Complaint Code			Part N	t No Part Des			scription Qua		Quantity	intity Billing Type		SE Analysis	
	CULPRIT PART	10	10071979AA	1	EXHAUST DU	CT (OVA	L TYPE)		1.00	WARRA			
Labour Detail(B)													
Complaint Code	Action 1	Taken				Labour C	ode		Labour	Hours		L	abour Charge
Data not available.													***************************************
Consumables C													
Complaint Code Description				Qty					Rate An			nount	
Data not available.													
OutsideJob (D)													
Complaint Code	Details of Job			BillNo					Date Ar			mount	
Data not available.													
Claim Summary													
Port(A)		-					-	-			***************************************		
Part(A) Outside Job (D)			Labour (B)						Consumable				
Cultime Job (D)			Sale Tax	(E)	C)			Total(A+B+C	C+D+E)	22850)	
Culprit Part No	1007197	9AA			Culprit Part N	ame							
	AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY. SC RAISED SCR-2700036-2023-158				Dealer Action Taken					Complaint status Close			

