

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

PRINT

Warranty Claim

2700036 DBR CODE ACI LTD DBR NAME Md. Sirazul BANGLADESH CUSTOMER NAME Amchottar, Nawdapara, City Islam COUNTRY NAME DEALER ADDRESS Piada Hat Road, Rajshahi, ACI MOTORS - RAJSHAHI DEALER NAME CUSTOMER ADDRESS BZDDJ1135516S3 Chassis No 2700036-9476B3-2023-140 JobCard No 22-Sep-2022 2700036-9476B3-2022-193 Job Card Date Warranty Claim No 4100FL24A1135845 22-Sep-2022 Engine No 60 RX SUPREME 2WD Date of Failure Tractor Model Last Service Date 3602806987 22-Sep-2022 Invoice No Date 477.00 Hours Worked 12-Apr-2022 BAD NOISE WAS COMING FROM THE SILENCER. Date of Sale **Customer Complaint** Last Service Hours Buyer Ref No 21-Jan-2022 Invoice Date 7th Service PDI & Service Details 6th Service 5th Service 4th Service 3rd Service 1st Service 2nd Service PDI 05-Feb-2022 Complaint Details Complaint Desc Complaint Code Sub Aggregates ENGINE-SILENCER NOISY Aggregates EN137 **ENGINE** SE Analysis Quantity **Billing Type** Part Description Complaint Code Failure Type Part No WARRANTY EXHAUST DUCT (OVAL TYPE) 1.00 CULPRIT PART NO 10071979AA Labour Detail(B) Labour Charge Labour Hours Labour Code **Action Taken** Complaint Code Data not available. Consumables C Qty Rate **Amount** Description Complaint Code Data not available. OutsideJob (D) BillNo Date Amount Complaint Code Details of Job Data not available Claim Summary Labour (B) Part(A) Consumables (C) Sale Tax (E) 0 Outside Job (D) Total(A+B+C+D+E) 22850 Culprit Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND Dealer Analysis THAT EXHAUST DUCT FAULTY, SCR Dealer Action Taken Close Complaint status RAISED SCR-2700036-2022-1359 PITTING MARKS OBSERVED ON FIP. Acknowledgement Date 29-Sep-2022 Remarks **CAM, INTERMEDIATE** GEARS. exige Done By DIPTENDU ROY



