## Consuce

## SONALIKA

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

## Warranty Claim

											PRINT	
COUNTRY NAME	BANGLADESH			DBR NAME		ACI LTD			DBR CODE		270	0036
DEALER NAME	ACI BOGRA BOGRA			DEALER AD	DRESS	Bogra			CUSTOMER NAME		Udd	Síhab lin ( jahanpur
CUSTOMER ADDRES	S										)	
Warranty Claim No	2700036-9476B3-2023-22			JobCard No		2700036-9476B3-2023-218		18 Chas	ssis No		DXCDJ12	1956853
Tractor Model	ALL ROUNDER 55 SUPREME			Engine No		4100FL24I1212532			Job Card Date		20-Jan-2023	
Date	20-Jan-2023			Last Service Date				Date	Date of Failure		20-Jan-2023	
Date of Sale	15-Nov-2022			Hours Worked		354.00			Invoice No		36028128	74
Last Service Hours				Customer Comp	plaint	BAD NOISE WAS COMING FROM THE SILENCER.		NG				
Invoice Date	21-Sep-2022			, Buyer Ref No								
PDI & Service Details										Committee of the latest design	No. of Concession, Name of Street, or other party of the Street, o	
PDI	1st Service	2nd Service	3rd S	ervice	4th Serv	rice	5th Service	6	oth Service		7th Service	,
05-Oct-2022												
Complaint Details												
Data not available.												
Part Details											THE CONTROL OF THE PARTY OF THE	***************************************
Complaint Code	Failure 1	Type	Part No	T	Part De	scription	-	Quantitu	Dilling	Tona	I ce a	nha)a
7,00,7,000	CULPRIT PART N		071979AA	EXHAUST DU	JCT (OVA	L TYPE)	1.0	Quantity	Billing WARRANT		SE An	aiyaia
Labour Detail(B)												
Complaint Code Action Taken				Labour Code				Labour Hours				ır Charge
Data not available.												
Consumables C												
Complaint Code				Qty				Rate Am			ount	
Data not available.												
OutsideJob (D)												,
Complaint Code	Details of Job			BillNo				Date		Ame	Amount	
Data not available.										Zank	John	
Claim Summary							les .					
Part(A)			Labour (B)				0-		(C)			The second secon
uteido lob (D)		Sale Tax (E)	•			Consumables (C) Total(A+B+C+D+E) 2			22850			
Culprit Part No	10071979	AA	Taxaba -	Out to Death	lane.	-		-				
Dealer Analysis	AFTER IN THAT EXH RAISED S	Culprit Part Name  Dealer Action Taken					Complain	t status	Clos	0		
			120-100	The second secon		The same of the sa		-		-		

