

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala, Jalandhar Road, Hoshiarpur

Warranty Claim

PRINT ACI LTD BANGLADESH DBR NAME DBR CODE 2700036 COUNTRY NAME **ACI DHAKA DHAKA** DEALER ADDRESS DHAKA CUSTOMER NAME DEALER NAME Supna CUSTOMER ADDRESS 2700036-9476B2-2022-55 2700036-9476B2-2023-21 JYASR1088709S3 Chassis No. Warranty Claim No JobCard No **DI 35 RX 2WD** 3100FL14H1084603 Job Card Date 20-Aug-2022 Tractor Model Engine No 20-Aug-2022 Date 20-Aug-2022 Last Service Date Date of Failure 3602802808 30-Nov-2021 Invoice No Date of Sale Hours Worked 731.00 BAD NOISE WAS COMING Last Service Hours Customer Complaint FROM THE REAR AXLE. Invoice Date 14-Aug-2021 Buyer Ref No PDI & Service Details PDI 7th Service 1st Service 2nd Service 5th Service 6th Service 3rd Service 4th Service 23-Aug-2021 Complaint Details Sub Aggregat Complaint Desc REAR AXLE RA02 REAR AXLE-AXLE SHAFT BEARING WORN Part Details Complaint Code Failure Type Part No Part Description Quantity Billing Type SE Analysis CULPRIT PART NO 20003761AA TAPPER ROLLER BEARING 3982/3920 WARRANTY Labour Detail(B) Complaint Code **Action Taken** Labour Code Labour Hours Labour Charge Data not available Consumables C Complaint Code Description Qty Rate Amount Data not available. OutsideJob (D) Complaint Code Details of Job BillNo Date Amount Data not available. Claim Summary Part(A) Labour (B) Consumables (C) Outside Job (D) Sale Tax (E) Total(A+B+C+D+E) 22850 Culprit Part No 20003761AA Culprit Part Name AFTER INSPECTION WE FOUND Dealer Analysis THAT TAPPER ROLLER BEARING Dealer Action Taken Complaint status Close HAS DAMAGED PLEASE Acknowledgement Acknowledgement Date 25-Aug-2022 Remarks SETTLE Acknowledge Done By Rodu ~ DIPTENDU ROY

