## Jego Co Sonalika

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

## Warranty Claim

									PRINT					
COUNTRY NAME DEALER NAME	the state of the s		ORE	DBR NAME DEALER ADDRE		DRESS	ACI LTD  ESS Jessore			DBR CODE  CUSTOMER NAME		2700036 Md Liton Hasan Tuku (Jashore)		
CUSTOMER ADDRESS	3													
Warranty Claim No	2700036-0	476B6-2023	-20		JobCard No		2700036-94	76B6 202	1-3	Chassi	is No		DYCD	R1107069S3
Tractor Model	2700036-9476B6-2023-20 ALL ROUNDER 55 SUPREME			Engine No			4100FL14I1101946			Job Card Date			05-Apr-2023	
Date	05-Apr-2023			Last Service Date			4100121411101940			Date of Failure		05-Apr-2023		
Date of Sale				Hours Worked			1135.00			Invoice No			3602803788	
Date of Sale	20-001-20	21			Hours Worked		BAD NOISE	WAS CO		IIIVOICE	NO		30020	33700
Last Service Hours					Customer Comple	aint	FROM THE							
Invoice Date	17-Sep-20	021			Buyer Ref No									
PDI & Service Details				-									act of Dags of the Charge of Section 19	
PDI	1st Service 2nd Servi		ce 3rd		ervice	4th Service		5th Service		6th Service			7th Service	
26-Sep-2021				-	-									
Complaint Details														
Data not available.														
Part Details													MATTER MATERIAL STATE OF THE ST	
Complaint Code		Failure Type Part N									and the same		SE	Analysis
_abour Detail(B)	CULPRIT PART	NO	10071979AA		EXHAUST DUC	JI (UVA	L ITPE)		1.00		WARRAN'	IY		
Complaint Code	Action	Taken			L	abour C	ode		Labou	ur Hou	ırs		La	bour Charg
Data not available.														
Consumables C														
Complaint Code	Desc	ription		-		C	ity	-	Rate			Amo	nunt	
Data not available.														
OutsideJob (D)														
Complaint Code	Detai	Details of Job		BillNo			illNo	Date			Amount			
Data not available.														
Claim Summary														
Part(A)			Labour (B	3)					Consumab	les (C	)	*********	THE PERSON NAMED IN	
Outside Job (D)			Sale Tax	(E)	0				Total(A+B+			22850		
Culprit Part No	10071979	PAA			Culprit Part Na	me								
Dealer Analysis	AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY, SCR RAISED SCR-2700036-2023-572				Dealer Action Taken					Complaint status Close				

