Jenson Sonalika

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

												PRIN	T		
COUNTRY NAME	BANGLADESH				DBR NAME		ACI LTD			D	DBR CODE			700036	
DEALER NAME	ACI MYMENSINGH				DEALER ADDRESS		Digharkanda, Chatrapara Aamlitola, Mymensingh			CUSTOMER NAME			Md. Masudur Rahaman		
CUSTOMER ADDRESS															
								7074 0000		01	- NI-		IVOD	1400740000	
Warranty Claim No	2700036-9476B1-2023-17 ALL ROUNDER 55 SUPREME				obCard No	2700036-9476B1-2023-82 4100FL24H1205036			Chassis No Job Card Date			JXCDJ1207168S3 09-Feb-2023			
Tractor Model Date	09-Feb-2023				Engine No ast Service Dat	•	41001 624111200000			Date of Failure			09-Feb-2023		
Date of Sale	19-Jan-2023				Hours Worked		81.00		Invoice No		3602812011				
Last Service Hours					Customer Comp	laint	BAD NOISE WAS COMING FROM THE EXHAUST DUCT.								
Invoice Date	23-Aug-2022				Buyer Ref No										
PDI & Service Details								-				australia internati			
				3rd Se	rvice	ice 5th Service			6th Service		7th Service				
10-Sep-2022															
Complaint Details															
Data not available.															
Part Details															
Complaint Code	omplaint Code Failure Type Part No		lo		cription Quant				SE	Analysis					
	CULPRIT PART N	0	10071979A	4	EXHAUST DU	CT (OVA	L TYPE)		1.00	1	WARRANT	Υ			
Labour Detail(B)															
Complaint Code Action Taken				Labour Code				Labour Hours				Labour Charge			
Data not available.															
Consumables C												*****************************	*****	***************************************	
Complaint Code	Description				Qty			Rate Amount				ount			
Data not available.															
OutsideJob (D)															
Complaint Code	Details of Job				BillNo				Date			Am	Amount		
Data not available.															
Claim Summary															
Part(A)			Labour	(B)				,	Consumal	bles (C)				
Outside Job (D)			Sale Tax		•	0		,	Total(A+B	+C+D+	E)	22850)		
Culorit Post No.					Cularit Port 1	lame									
Culprit Part No	10071979				Culprit Part N										
Dealer Analysis	AFTER IN	ISPECTION I	WE FOUND		Dealer Action	Taken					Complair	t status	(lose	

