Prings Sonalika

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

					,							PRI	NT		
COUNTRY NAME	BANGLADESH			DBR NAME			ACI LTI	ACILTD DBR C					0.000		
DEALER NAME	ACI MOTORS - RAJSHAHI			DEALER ADDRESS			Amchottar, Nawdapara, City Hat Road, Rajshahi,			City	CUSTOMER NAME			Md. Golam Rabbani	
CUSTOMER ADDRESS	3														
COSTONIETTASSACTO															
M t. Claim No.	2700036-94	76B3-2023-35		Job	Card No		2700036-947	6B3-202	3-231	Chas	ssis No		DZDI	DR1104499S	
Warranty Claim No Tractor Model	60 RX SUPREME 2WD			Engine No			4100FL14I1100575 Job			Job	b Card Date		16-Feb-2023		
Date	16-Feb-2023			Last Service Date						of Failure 16-Feb-202			eb-2023		
Date of Sale	05-Oct-2021			Hours Worked			1485.00			Invo	ce No		3602	803754	
				Cus	tomer Compla	int	ROTAVATOR	COULD	NOT						
Last Service Hours				Buyer Ref No											
Invoice Date	16-Sep-202	-		Duy	el Kel No										
PDI & Service Details										_					
PDI	1st Service 2nd Service		3rd	3rd Service		4th Service		5th Service			6th Service		7th Service		
24-Sep-2021															
Complaint Details															
Data not available.															
Part Details															
Complaint Code Failure Type Pai			Part No	No Part Description			Quantity		Billing Type		3	E Analysis			
Complaint Code	CULPRIT PART N		0012651AB		FEATHERING				1.00		WARRAN				
abour Detail(B) Complaint Code Action Taken				Labour Code					Labour Hours				ı	abour Charg	
Data not available.															
Consumables C															
Complaint Code	omplaint Code Description				Qty				Rate Amo				ount		
Data not available.															
OutsideJob (D)															
Complaint Code	Details of Job				BillNo			*****	Date			Am	Amount		
Data not available.															
Claim Summary															
Part(A)	Labour (I						Consumables (C)								
Outside Job (D)			Sale Tax (E	:)	0				Total(A+	B+C+	D+E)	2285	0		
Culprit Part No	10012651			(Culprit Part Na	me									
Dealer Analysis	AFTER INSPECTION WE FOUND THAT FEATHERING VALVE COULD NOT BUILD PRESSURE.				Dealer Action Taken						Compla	int status		Close	

