

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

The Details Complaint Code Failure Type Part No Part Description Quantity Billing Type SE Analysis CULPRIT PART NO 10071979AA EXHAUST DUCT (OVAL TYPE) 1 00 WARRANTY Abour Detail(B) Complaint Code Action Taken Labour Code Labour Hours Labour Charge Data not available. Complaint Code Description Otly Rate Amount Data not available. Complaint Code Description Otly Rate Amount Data not available. Complaint Code Details of Job BilliNo Date Amount Data not available. Alta not available.					1	Warrant	y Cla	31111						
DEALER ADDRESS DER NAME ACTION											12F 17			
DEALER NAME ACIBARISAL Burisal DEALER ADDRESS CUSTOMER ADDRESS	COUNTRY NAME	BANGLADESH			DBR NAME			ACI LTI	ACI LTD					
Variety Claim No		ACI BARISAL Barisal				DEALER ADDRESS Ba			sal CUSTO					
Movementy Claim No	CUSTOMER ADDRESS	3												
Warranty Claim No								2700026 0/	76B3_2023	-138 Ch	assis No		GZGE	J1163965S3
Transfor Model	Warranty Claim No			-191								e	22-Se	p-2022
Date of Service Process of Service Ser							ite	31001111211		Da	ate of Failur	e		
Customer Complaint Exist Service Hourn POL 5 Service Date 22 Agr-2022 Buyer Ref No											voice No		36028	309248
DOLS Service Date Service Petals Sub Aggregates Sub Aggregates Complaint Code Complaint Desc Super Part No Service Sub Aggregates Sub Aggrega		10 00. 202	_		(Customer Comp	plaint	BAD NOISE	E WAS CON	MING				
DI & Service Details DI Service Details DI Service State S		22-Anr-202	22					FROM THE	SILLINGLI					
State Service	Invoice Date	22-hpi-201												
Sub Aggregates Sub Aggregates Complaint Code Complaint Desc	DI & Service Details						I		5th Sand	<u> </u>	6th Servi	ce	7th Se	rvice
omplaint Details Complaint Details		1st Service	2nd Service	ce	3rd Se	ervice	4th Sen	VICE	oth Service		Citi Collin			
Sub Aggregates Sub Aggregates Complaint Code Complaint Desc	0-May-2022		-				_							
Sub Aggregates Sub Aggregates Complaint Code Complaint Desc	omplaint Details													
Action Taken Entity			Sub Aggre	enates			Compla	int Code			Complai	nt Desc		
Complaint Code Failure Type Part No Part Description Quantity Billing Type SE Analysis CULPRIT PART NO 10071979AA EXHAUST DUCT (OVAL TYPE) 1.00 WARRANTY Description Code Action Taken Labour Code Labour Hours Labour Charge Consumables C Complaint Code Description Offy Rate Amount Code Complaint Code Details of Job BilliNo Date Amount Code Complaint Code Code Code Code Code Code Code Code	Aggregates ENGINE		Sub Aggre	egates				int occur			ENGINE-	SILENCER N	IOISY	
Complaint Code Failure Type Part No Part Description Quantity Billing Type SE Analysis CULPRIT PART NO 10071979AA EXHAUST DUCT (OVAL TYPE) 1.00 WARRANTY Description Code Action Taken Labour Code Labour Hours Labour Charge Consumables C Complaint Code Description Offy Rate Amount Code Complaint Code Details of Job BilliNo Date Amount Code Complaint Code Code Code Code Code Code Code Code														
Complaint Code Faiture type Part No 10071979AA EXHAUST DUCT (OVAL TYPE) 1.00 WARRANTY abour Detail(B) Complaint Code Action Taken Labour Code Labour Hours Labour Charge Complaint Code Action Taken Labour Code Labour Hours Labour Charge Complaint Code Description Otly Rate Amount Data not available. Complaint Code Description Otly Rate Amount Data not available. Complaint Code Details of Job BillNo Date Amount Data not available. 2015 Anot available. 2016 Anot available. 2017 Anot available. 2018 Anot available. 2018 Consumables (C) Total(A+B+C+D+E) 22850 2019 Anot available. 2019 Anount Date Another Consumables (C) 2019 Anot available. 2019 Anount Date Another Consumables (C) 2019 Anount Date (C) 2019 Another Consumables (C) 201	art Details									_	1 0		T 6	E Analysis
pactor Petri No Residence Labour Code Labour Hours Labour Charge Labour Hours Labour Charge Labour	Complaint Code					EVHALIST DI							-	E Analysis
Data not available. Onsumables C Complaint Code Description Oily Rate Amount Data not available. UtsideJob (D) Omplaint Code Details of Job Bill No Date Amount Data not available. In Code Details of Job Bill No Date Amount Data not available. In Consumable (C) Total(A+B+C+D+E) 22850 Utside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 Utside Job (D) Sale Tax (E) Dealer Action Taken Complaint status Close Complaint Code Details of Job Bill No Date Amount Date Amount Date Amount Date Amount Consumables (C) Total(A+B+C+D+E) 22850 Dealer Action Taken Complaint status Close Complaint Sale ScR-2700036-2022-1359 Dealer Action Taken Complaint status Close Chrowledgement Yes Acknowledgement Date 29-Sep-2022 Remarks SQUND OBSERV ORDERNAL SCR-2700036-2022-1359 Dealer Action Taken Complaint Sale SCR-2700036-2022-1359 Dealer Action Taken Complaint Sale SQUND OBSERV Approved Date Remarks	abour Detail(B)	COLFRIT	10	1007197970	`	EXTROSTER	001(01/							
omplaint Code Description Ohy Rate Amount atta not available. JustideJob (D) Omplaint Code Details of Job BillNo Date Amount Data not available. JustideJob (D) Amount Data not available. JustideJob (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 Justide Job (D) Total(A+B+C+D+E) 228	complaint Code	e Action Taken				Labour Code			Labour Hours				ı	abour Charge
Complaint Code Description Qty Rate Amount Data not available. UnsideJob (D) Complaint Code Details of Job BillNo Date Amount Data not available. Consumables (C) Total(A+B+C+D+E) 22850 Diprit Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND THAT EXHAUST DUT FAULTY. SCR RAISED SCR-2700036-2022-1359 Dealer Action Taken Complaint status Close RATTLIN SOUND OBSERV Sproval Approved Date Remarks	Data not available.													
Data not available. Details of Job Details of Job Date Amount Data not available. Data Summary Data Summary Data Summary Duprit Part No Data Notai(A+B+C+D+E) 22850 Data Notai(A+B+C+D+E) 22850 Data Notai(A+B+C+D+E) 22850 Data Notai(A+B+C+D+E) 22850 Duprit Part No Data Notai(A+B+C+D+E) 22850 Duprit Part Nome Approved Data Data Notai(A+B+C+D+E) 22850 Data N	onsumables C													
Data not available. Details of Job BillNo Date Amount Data not available. Data not availab	Complaint Code	Desc	ription					Qty		Rate		Ап	nount	
omplaint Code Details of Job BillNo Date Amount Data not available. aim Summary art(A) Labour (B) Consumables (C) Utside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 Utpirt Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY SCR RAISED SCR-2700036-2022-1359 Dealer Action Taken Complaint status Close RATTLIN SOUND OBSERV Approved Date Remarks														
omplaint Code Details of Job BillNo Date Amount Data not available. aim Summary art(A) Labour (B) Consumables (C) Uside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 ulprit Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY, SCR RAISED SCR-2700036-2022-1359 Cknowledgement Yes Acknowledgement Date 29-Sep-2022 Remarks Chrowledge Done By DIPTENDU ROY Approved Date Remarks														
Data not available. alm Summary art(A) Labour (B) Consumables (C) utside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 utprit Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY. SCR RAISED SCR-2700036-2022-1359 Cknowledgement Yes Acknowledgement Date 29-Sep-2022 Remarks SOUND OBSERV proval Approved Date Remarks	utsideJob (D)													
art(A) Labour (B) Consumables (C) Utside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 Ulprit Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY SCR RAISED SCR-2700036-2022-1359 Cknowledgement Yes Acknowledgement Date 29-Sep-2022 Remarks SOUND OBSERV Oproval Approved Date Remarks	omplaint Code	Detai	ls of Job					BillNo		Date		Ar	nount	
art(A) Labour (B) Consumables (C) utside Job (D) Sale Tax (E) 0 Total(A+B+C+D+E) 22850 ulprit Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY. SCR RAISED SCR-2700036-2022-1359 cknowledgement Yes Acknowledgement Date 29-Sep-2022 Remarks SOUND OBSERV Opproval Approved Date Remarks	Data not available.													
utside Job (D) Sale Tax (E) O Total(A+B+C+D+E) 22850 utprit Part No utprit Part No ealer Analysis AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY. SCR RAISED SCR-2700036-2022-1359 Dealer Action Taken Complaint status Close RATTLIN SOUND OBSERV proval Approved Date Remarks	alm Summary													
utside Job (D) Sale Tax (E) O Total(A+B+C+D+E) 22850 utprit Part No utprit Part No ealer Analysis AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY. SCR RAISED SCR-2700036-2022-1359 Dealer Action Taken Complaint status Close RATTLIN SOUND OBSERV proval Approved Date Remarks	art(A)			Labour	(B)					Consumah	les (C)			
ulprit Part No 10071979AA Culprit Part Name AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY. SCR RAISED SCR-2700036-2022-1359 Cknowledgement Yes Acknowledgement Date 29-Sep-2022 Remarks SOUND OBSERV Oppoval Approved Date Remarks	utside Job (D)			Sale Ta	x (E)		0					228	50	
AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY. SCR RAISED SCR-2700036-2022-1359 Dealer Action Taken Complaint status Close RATTLIN Cknowledgement Yes Acknowledgement Date 29-Sep-2022 Remarks RATTLIN SOUND OBSERV Dealer Action Taken Acknowledgement Date 29-Sep-2022 Remarks Remarks											,			
THAT EXHAUST DUCT FAULTY. SCR RAISED SCR-2700036-2022-1359 Dealer Action Taken Complaint status Close Complaint status Close RATTLIN SOUND OBSERV Dealer Action Taken Acknowledgement Date 29-Sep-2022 Remarks RATTLIN SOUND OBSERV Dealer Action Taken Acknowledgement Date 29-Sep-2022 Remarks Remarks	ulprit Part No	10071979)AA		_	Culprit Part	Name							
Acknowledgement Date 29-Sep-2022 Remarks SOUND OBSERV cknowledge Done By DIPTENDU ROY Approval Approved Date Remarks	ealer Analysis	THAT EX	HAUST DUC	T FAULTY. S	CR	Dealer Actio	n Taken				Cor	mplaint status	5	Close
pproval DIPTENDU ROY Approved Date Remarks	cknowledgement	Yes			A	cknowledgeme	nt Date	2	9-Sep-2022		Ren	narks		
Remarks	cknowledge Done By	DIPTENDU	ROY											GOGENY
	proval				Ą	pproved Date					Ren	narks		
* · · · · · · · · · · · · · · · · · · ·														

