

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

## Warranty Claim

PRINT 2700036 DBR CODE ACI LTD DBR NAME BANGLADESH Rafikul COUNTRY NAME CUSTOMER NAME DHAKA Islam DEALER ADDRESS ACI DHAKA DHAKA DEALER NAME CUSTOMER ADDRESS AYASR1047218S3 Chassis No 2700036-9476B1-2023-34 JobCard No 2700036-9476B1-2022-41 23-Sep-2022 Job Card Date Warranty Claim No 3100FL14D104280400 Engine No 23-Sep-2022 DI 35 RX 2WD Date of Failure Tractor Mode Last Service Date 3602812539 23-Sep-2022 Invoice No Hours Worked 22-Dec-2021 FRONT AXLE BKT HAS Date of Sale **Customer Complaint** CRACKED. Last Service Hours Buyer Ref No 31-Mar-2021 Invoice Date PDI & Service Details 7th Service 6th Service 5th Service 4th Service 3rd Service 2nd Service 1st Service PDI 04-May-2021 Complaint Details Complaint Desc Complaint Code Sub Aggregates FRONT AXLE -SUPPORT BROKEN Aggregates FA16 FRONT AXLE Part Details SE Analysis **Billing Type** Quantity Part Description Part No Complaint Code Failure Type WARRANTY INTEGRAL FRONT AXLE BKT 1.00 CULPRIT PART NO 10070250EA Labour Detail(B) Labour Charge **Labour Hours** Labour Code **Action Taken** Complaint Code Data not available. Consumables C **Amount** Rate Qty Description Complaint Code Data not available. OutsideJob (D) **Amount** BillNo Date Details of Job Complaint Code Data not available. Claim Summary Labour (B) Consumables (C) Part(A) Total(A+B+C+D+E) 22850 Sale Tax (E) Outside Job (D) Culprit Part No 10070250EA Culprit Part Name AFTER INSPECTION WE FOUND CRACK MARK ON INTEGRAL **Dealer Analysis** Dealer Action Taken Complaint status Close FRONT AXLE BKT. SCR RAISED SCR-2700036-2022-1351 Acknowledgement FRONT AXLE Acknowledgement Date 29-Sep-2022 Remarks BRACKET GOT CRACKED DUE TO STRESS



