## SONALIKA

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

## Warranty Claim

						,					PRI	NT	1
COUNTRY NAME	BANGLADESH			DBR NAME			ACI LTD			DBR CODE			2700036
DEALER NAME	ACI JESSORE JESSORE			DEALER ADDRESS			Jessore			CUSTOMER NAME		Md. Hafijur Rahman Sardar (Khulna)	
CUSTOMER ADDRESS													(
Warranty Claim No	2700036-9476B6-2023-6			JobCard No			2700036-9476B6-2023-52		2 Ch	Chassis No		BZGDJ1136137S3	
Tractor Model	DI 50 RX S		2WD		ngine No		3105NH24A	1139229		Card Date			n-2023
Date	19-Jan-2023 10-May-2022				Last Service Date Hours Worked					te of Failure		19-Jan-2023 3602807277	
Date of Sale	10-мау-20	22			ustomer Comp	la:nt	699.00 LUBRICANT	OIL	inv	oice No		3602	507277
Last Service Hours	30-Jan-20	22				ant	OVERLOAD	ED.					
Invoice Date	30-Jan-20	22		ы	uyer Ref No								
PDI & Service Details							100 and						
	1st Service	2nd Serv	rice	3rd Serv	/ice	4th Serv	lce	5th Service		6th Service	•	7th Sei	rvice
08-Feb-2022													
Complaint Details		J											
Data not available.													
Part Details								g-1-2000-0-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-			***************************************		***************************************
D 1 ( 1 D )	F-W T									. 1		1 42	
Complaint Code	Failure Ty CULPRIT PART N		Part No 800402020B		D. PUMP ASS		cription 4 mtg. Lift		Quanti 1.00	WARF	ling Type	S	E Analysis
_abour Detail(B)							<u> </u>						
Complaint Code	Action	Taken				Labour (	ode		Labour	Hours		L	abour Charge
Data not available.													
Consumables C													
Complaint Code	Desc	cription				(	Qty		Rate	omitted and a second	Am	ount	
Data not available.											7,000	·oun	
OutsideJob (D)													
									-				
Data not available.	Details of Job				BillNo			Date			Amount		
Data not available.										-			-
Claim Summary													
Part(A)			Labour	(B)				·	one imah!	e (C)			AND REAL PROPERTY AND THE PARTY AND THE PART
Outside Job (D)	Sale Tax							Consumables (C) Total(A+B+C+D+E) 228			2285	0	
Culprit Part No	2004200	20B	-		Culorit Part N	lame							
Dealer Analysis	800402020B  AFTER INSPECTION WE FOUND  THAT OIL SEAL OF HYDRAULIC  PUMP LEAKED AND SO HYDRAUL				Culprit Part Name  IC Dealer Action Taken								
			TH LUBRICAN							Compl	aint status		Close

