How M SONALIKA

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala, Jalandhar Road, Hoshiarpur

Warranty Claim

	BANAL ISSAU		DDD NAME			ACUTO		PRINT			
COUNTRY NAME	A STATE OF THE PARTY OF THE PAR			DBR NAME			ACILTO		DBR CODE		2700036 Md. Pear
DEALER NAME			DEALER ADDRESS		Gazi	Gazipur		CUSTOMER NAME		All	
CUSTOMER ADDRESS	S										_
					-					JZDDJ121558	
Warranty Claim No	2700036-9476B2-2022-70				9476B2-2023-36 H1207774				3553		
Tractor Model Date	60 RX SUPREME 2WD 04-Dec-2022		Last Service Date		111207114		lob Card Date 04-Date of Failure 04-Date				
Date of Sale	31-Oct-2022		Hours Worked 149.00				nvoice No 38028122				
Last Service Hours				Customer Comp	laint		G OIL WAS COMING	3			
Invoice Date	29-Aug-2022	2		Buyer Ref No		r KOW II	ie oreerinor ii e.				Married II
								4	and the same of the		
PDI & Service Details			1	-	44.0		5th Service	6th Se	rvice	7th Service	
PDI	1st Service	2nd Service	3rd S	ervice	4th Serv	rice	Stil Service	0.110	,,,,,,,		
12-Sep-2022	-				-						
Complaint Details						77.75					-
No reaction	[6	iuh Acgregates	-		Complai	nt Code		Comp	laint Desc		
Aggregates STEERING SYSTEM	Sub Aggregates			Complaint Code ST18				STEERING -PIPE JOINTS LEAKAGE			
Part Details											
art Details	and the state of t						AND THE RESERVE AND THE PARTY OF THE PARTY O		T	Ici	
Complaint Code	Failure Type	Part No	DIDE E	ROM STEERING	art Des		GCY	1.00	WARRANTY	ne SE Ann	y
ahaw Datail/B\	CULPRIT PART NO	10039471AB	PIPEFF	OM STEERING	UNITE	JOSTELINIA	001	1100			
abour Detail(B)											
Complaint Code	Action Ta	ken			Labour (Code	Lal	our Hours		Labour (Charg
Data not available.									-		-
onsumables C											
							D-4		۸-	nount	
Complaint Code	Description		Qty		Rate		All	Attour			
Data not available.	<u> </u>			SAC - CONTRA			-	and the state of			THE STATE OF
OutsideJob (D)				oles in the second second second second	-						-
Complaint Code	Details	of Job				BillNo	Dat	е	Ar	nount	-
Data not available.											-
Claim Summary											
		and the second s					0	mables (C)			
Part(A)			ur (B)				-	+B+C+D+E) 228	50	
Outside Job (D)		Sale	Tax (E)		0		Total(A	**********	1 220	,,	
					40. eks						
and the same of the same of	10039471AB		Culprit Part I	Vame							
Culprit Part No			ND	Dealer Action	Taken				Complaint status	Close	
Culprit Part No	AFTER INS	FROM STEERING	UNIT								
	AFTER INS THAT PIPE LEFT TO S	PECTION WE FOU FROM STEERING TEERING CYLINDE	UNIT	Dealer Action		CHECK THE PARTY	A STATE OF THE PARTY OF THE PAR				BATTE A
Dealer Analysis	AFTER INS THAT PIPE LEFT TO S LEAKAGE.	FROM STEERING	UNIT		ent Date		12-Dec-2022		Remarks		
Culprit Part No Dealer Analysis Acknowledgement	AFTER INS THAT PIPE LEFT TO S LEAKAGE.	FROM STEERING TEERING CYLINDE	UNIT	Acknowledgem	ent Date		12-Dec-2022		Remarks		
Dealer Analysis	AFTER INS THAT PIPE LEFT TO S LEAKAGE.	FROM STEERING TEERING CYLINDE	UNIT	Acknowledgem			12-Dec-2022		Remarks		
Dealer Analysis Acknowledgement Acknowledge Done By Approval	AFTER INS THAT PIPE LEFT TO S LEAKAGE.	FROM STEERING TEERING CYLINDE ROY	UNIT				12-Dec-2022				
Dealer Analysis Acknowledgement Acknowledge Done By Approval Approval Done By	AFTER INS THAT PIPE LEFT TO S LEAKAGE.	FROM STEERING TEERING CYLINDE ROY	UNIT	Acknowledgem			12-Dec-2022				
Dealer Analysis Acknowledgement Acknowledge Done By Approval Approval Done By Payment	AFTER INS THAT PIPE LEFT TO S LEAKAGE.	FROM STEERING TEERING CYLINDE	UNIT	Acknowledgem Approved Date			12-Dec-2022		Remarks	s	ETTL
Dealer Analysis Acknowledgement Acknowledge Done By	AFTER INS THAT PIPE LEFT TO S LEAKAGE.	FROM STEERING TEERING CYLINDE	UNIT	Acknowledgem Approved Date			12-Dec-2022 PENDING FOR A	PPROVAL	Remarks	s 	

