Hanika Mind

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

COUNTRY	B.111-1	ADEC!:								PRI	INT	
COUNTRY NAME	BANGLADESH			DBR NAME				ACI LTD		DE 270		2700036
DEALER NAME	DEALER NAME ACI GAZIPUR GAZIPUR		DEALER ADDRESS			Gazipur		CUSTOMER NAME			SS Agro	
CUSTOMER ADDRESS	3	<u> </u>										
Warranty Claim No	2700036-9	9476B2-2022-80		1.10								
Tractor Model	60 RX SUPREME 2WD			JobCard No			2700036-9476B2-2023-47		Chassis No		EZDDR1084045S3	
Date	29-Dec-2022			Engine No Last Service Date			4100FL14G1078489		Job Card Date		29-Dec-2022	
Date of Sale 31-Aug-2021				Hours Worked			1128.00		Date of Failure			
							FUEL METE	R AND	Invoice No		360280	2412
Last Service Hours				Customer Complaint			TEMPERATURE METER WAS NOT SHOWING PROPER READING.					
Invoice Date 27-Jul-2021				Buyer Ref No			READING.					
PDI & Service Details												
PDI	1st Service 2nd Service		3rd	3rd Service		4th Service 5		5th Service	6th Service		7th Service	
14-Aug-2021												
Complaint Details												
Data not available.										Arm of the same of	-	W.110-18-18-18-18-18-18-18-18-18-18-18-18-18-
Part Details												Marine and the second street against
												-
Complaint Code							Part Description		Billing Type		SE	Analysis
		10001691A				ENSOR UNIT		WARRANTY	WARRANTY			
abour Detail(B)								1.00	WARRANTY			
Complaint Code	Action T	aken			La	bour Co	de	Labo	our Hours			Charge
Data not available.								Labo	our nours		Lat	our Charge
consumables C												
Complaint Code	Descri	ntion			-	Qty						
Data not available.				City Rate					Amount			
utsideJob (D)												
omplaint Code Details of Job				BillNo Date					Amount			
Data not available.								Date		Amot	ını	-
laim Summary												
'art(A)												
Outside Job (D)		Labour (B) Sale Tax (I						Consumables (C) Total(A+B+C+D+E) 22850				
			- van (E)		U			iotal(A+B-	+C+D+E)	22850		
Culprit Part No	· ·		_									
	10022398A		OLIND	Culprit	t Part Nam	ne						
Oneles to 1	AFTER INSPECTION WE FOUND THAT TANK UNIT AND TEMPERATURE SENSOR UNIT FAULTY.				Dealer Action Taken							