

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

								PRINT				
				DBR NAME		ACI LT	TD	DBR CC	DE	27	00036	
COUNTRY NAME				DEALER ADDRESS			Gazipur		CUSTOMER NAME		d.Atik asan	
DEALER NAME				DETERMINE								
CUSTOMER ADDRES	SS											
						2700036.0/	176B2-2023-33	Chassis No		FZDDJ1	17346683	
Warranty Claim No	2700036-9476B2-2022-67		JobCard No Engine No			2700036-9476B2-2023-33 4100FL24E1171130		Job Card Date		26-Oct-2022		
Tractor Model	60 RX SUPREME 2WD 26-Oct-2022			Last Service Date			C		Date of Failure		2022	
Date	31-Aug-2022			Hours Worked				Invoice No		360281	0070	
Date of Sale	51-Aug 20					STEERING FROM THE	OIL WAS COMING	3			1	
Last Service Hours			Customer Complaint STE			STEERING	SUNIT TO SCYLINDER.					
Invoice Date	27-May-20	122	В	Buyer Ref No								
PDI & Service Details								1		741 0		
PDI a Service Detaile	1st Service	2nd Service	3rd Sen	vice	4th Servi	ce	5th Service	6th Servi	ce	7th Servi	ce	
19-Jul-2022												
19-50, 200												
Complaint Details										-		
		Cub Assessable			Compla	int Code		Compla	int Desc			
Aggregates		Sub Aggregates		Complaint Code				STEERING -POWER STEERING PUMP				
STEERING SYSTEM	EERING SYSTEM			ST16				LEAKAGE				
Part Details												
Complaint Code	Failure Type	Part No			Part Des	cription		Quantity	Billing Ty	100	E Analysis	
Complaint Code	CULPRIT PART NO	10039472AB	PIPE FRO	OM STEERING	UNIT R 1	O STEERIN	GCY	1.00	WARRANT			
Labour Detail(B) Complaint Code	Action	Taken			Labour	Code	La	bour Hours		La	bour Charge	
Data not available.												
Consumables C												
Complaint Code	nplaint Code Description			Qty Ri				ate Amount				
Data not available.												
OutsideJob (D)												
Compleies Code	Details of Job			BillNo			Da	ite	,	Mount		
Complaint Code												
Data not available.												
Claim Summary												
		Lab	our (B)				Cons	umables (C)				
Part(A)			e Tax (E)		0			A+B+C+D+E)	22	850		
Outside Job (D)		San	6 18X (C)		•		Total	ATBTCTUTE	22	650		
Culprit Part No	1003947	72AB		Culprit Part	Name							
Dealer Analysis	AFTER INSPECTION WE FOUND THAT RIGHT SIDE PIPE FROM STEERING UNIT TO STEERING CYLINDER HAS LEAKED.			Dealer Action Taken				C	omplaint sta	tus	Close	
Acknowledgement	Yes			Acknowledge	ment Dat	e	03-Nov-2022		Remarks		PLEA	
Acknowledge Done By	DIPTEN	DU ROY										
Approval		(rygon)	N	Approved Dat	10				Remarks			
Approval Done By		V. gan		_								
Payment		(cr		Payment Date					Remarks			
Payment Done By		•										

