SONALIKA

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

| | | | | | | | | PRINT | | | | | |
|-----------------------------|--|------|-----------|---------------------|---------------------|-------------------------|-----------------------|-------------|--------------|----------------------------|--|---------------------------|--|
| COUNTRY NAME | BANGLA | DESH | | | DBR NAME | - | ACI LT | D | | DBR CO | DE | | 2700036 |
| DEALER NAME | ACI BOGRA BOGRA | | | DEALER ADDRESS | | | Bogra | | | CUSTOMER NAME | | | Md. Mamunur Rashid |
| CUSTOMER ADDRESS | 3 | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Warranty Claim No | 2700036-9476B3-2023-20 | | | | obCard No | 2700036-9476B3-2023-216 | | -216 Cha | Chassis No | | MXCDJ1137250S3 | | |
| Tractor Model | ALL ROUNDER 55 SUPREME | | | Engine No | | | 4100FL24B1145052 | | | Job Card Date | | 22-Jan-2023 | |
| Date | 22-Jan-2023 | | | Last Service Date | | | | | | Date of Failure Invoice No | | 22-Jan-2023 3602808124 | |
| Date of Sale | 10-May-202 | 22 | | H | lours Worked | | 1199.00 | | | oice No | | 36020 | 308124 |
| Last Service Hours | | | | C | Customer Compl | aint | BAD NOISE FROM THE | | | | | | |
| Invoice Date 28-Feb-2022 | | | | Е | Buyer Ref No | | | | | | | | |
| PDI & Service Details | | | | | - | | | | | | | | THE PART OF THE PA |
| PDI | 1st Service 2nd Service | | е | 3rd Service 4 | | th Service 5th | | 5th Service | | 6th Service | | 7th Service | |
| 15-Mar-2022 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Complaint Details | | | | | | | | | | | | | |
| Data not available. | | | | | | | | | | | | | |
| | | | | | | | | | | | and the contract of the contra | | |
| Part Details | | | | | | | | | | | | | |
| Complaint Code | plaint Code Failure Type Part | | | No Part Description | | | | Qua | | Billi | Billing Type | | E Analysis |
| | CULPRIT PART N | 0 | 10071979A | A | EXHAUST DU | CT (OVA | L TYPE) | | 1.00 | WARRA | NTY | | |
| Complaint Code Action Taken | | | | | Labour Code | | | | Labour Hours | | | Labour Charge | |
| Data not available. | | | | | | | | | | | | | |
| Consumables C | | | | | | | | | | | | | |
| Complaint Code | Description | | | | Qty | | | | Rate Amo | | | ount | |
| Data not available. | | | | | | | | | | | | | |
| OutsideJob (D) | | | | | | | | | | | | | |
| Complaint Code | Details of Job | | | | BillNo | | | | Date | | | Amount | |
| Data not available. | | | | | | | | | | | | | |
| Claim Summary | | | | | | | | | | | | | |
| Part(A) | | | Labour | (B) | | | | | Consumable | s (C) | | | |
| Outside Job (D) | | | Sale Ta | | C | | | | Total(A+B+C | | 22850 | 0 | |
| Culprit Part No | 10071979 | AA | - | | Culprit Part N | ame | | | | | | | |
| Dealer Analysis | AFTER INSPECTION WE FOUND THAT EXHAUST DUCT FAULTY. SO RAISED SCR-2700036-2023-158 | | | | Dealer Action Taken | | | | | Complaint status Close | | | |

